### ATTACHMENT D5-3

**Communication with WDEQ LQD related to Drill Hole Abandonment** 

NCRO-

OCT 27'87

# Texasgulf Minerals and Metals, Inc.

P.O. Box 191 2755 State Highway 67 Victor, Colorado 80860

Cripple Creek and Victor Operations (303) 689-2977

September 16, 1987

Richard G. Stockdale State Engineer's Office Herschler Building Cheyenne, WY 82002

> Re: Permit Nos. U.W. 61528 through U.W. 61539

Dear Mr. Stockdale:

In response to your letter regarding the above referenced monitor wells, theses specific wells were abandoned by Texasgulf in 1985. these wells were installed to monitor ground water quality on mining claims under Texasgulf's control. The claims were subsequently dropped by the company. As part of the procedure, the monitor wells were abandoned.

Enclosed is specific data on how each monitor well was abandoned. In each case, as much of the casing pipe as possible was pulled and the hole filled with concrete.

If you have further questions, please contact us.

Sincerely,

C. Allen Jappe

C. Alan Tapp Manager Cripple Creek Operations

CAT/kl

xc: Gonzalo Tufino William Strait Files (2)



MITTE TEXASCULF INC

5932 NCINTYRE STREET )RESS

P.03 GOLDEN CO 80403

14:44

JUL-10-2006

#### APPROVED AUGUST 1982

AUGUST 1987 REVIEW

LOCATION IF WELL IS ABANDONED PLEASE PROVIDE: IF STILL NAME OF ERNUT UMBER MONITORING REASON METHOD WELL 1/4 1/4, SEC-TWP-RGE DATE SHOW LIFE ...... 20-25-92 20-25-92 NWŻ NWŻ 61528 M-25-92-20-1S Filled with Concrete. 11-6-85 11-6-85 Property Abandonment M-25-92-20-1M NWY NWY Procerty Abandonment Filled with Concrete 1 61529 NHE NHE 20-25-92 11-6-85 赤 RI 61530 M-25-92-20-1D Property Abandonment Filled with Concrete 11-7-87 85 NET NET **⊣** ₹ 61531 M-25-92-19-3M 19-25-92 Property Abandonment Filled with Concrete 19-25-92 11-8-87 85 Property Abandonment NEŁ NE Filled with Concrete M-25-92-19-2M 1 61532 NEZ NE 19-25-92 11-8-87 55 M-25-92-19-1M Property Abandonment Filled with Concrete N 61533 SET SE 18-25-92 11-8-87 855 Property Abandonment Filled with Concrete ₩ 61534 M-25-92-18-1M 11-8-87 85 SET SET 18-25-92 Property Abandonment Filled with Concrete W 61535 M-25-92-18-1S SET SET 18-25-92 11-8-87 55 Property Abandonment Filled with Concrete W 61536 M-25-92-18-1D SWE SWE M-25-92-17-15. 17-25-92 11-7-85 Property Abandonment Filled with Concrete W 61537 SWE SWE 17-25-92 11-7-85 Property Abandonment Filled with Concrete M-25-92-17-1M W 61538 SWE SWE M-25-92-17-1D 17-25-92 11-7-85 Property Abandonment Filled with Concrete W 61539 ĨŴ ĵ₩ JW JW มีพ ์เพ MUMIT . . GROUND RECENT บิพิ ŨŴ ŪW UW ŪW  $\overline{0W}$ UW UK UW Ū₩ ŨŴ TW 27 The second card

C. Clan line in gent for fingelf

9-17-87

# Texasgulf memo

DateAugust 22, 1983ToD. C. EdmistonLocationGoldenFromC. Alan TappLocationGoldenSubjectLost Creek/Conoco - 1983 Program Summary

In a letter to Wyoming's DEG, November 24, 1982, Texasgulf outlined in detail its 1983 program for the Lost Creek/Conoco property. The program as outlined to Mr. Roy Spears presented a remedial plan, which once completed would rescind a Notice of Violation issued to Texasgulf on May 20, 1982. The program was initiated as outlined in June, 1983 and completed in late July, 1983. Approximately seventy-five percent of Texasgulf's Lost Creek/Conoco property was inventoried, the remainder will be completed in 1984.

Appendix B details Texasgulf's 1983 plan as presented to the DEQ. Basically, it involved inspecting down the hole conditions for every Texasgulf drill hole to determine the adequacy of past sealing efforts. Water levels and mud column depths were measured and recorded. Concrete caps were placed on all Texasgulf holes which were not originally capped with concrete or if the original concrete cap had failed. Appendix C listed the detailed results of the survey while Appendix D lists a section by section summary. Plate I indicates those sections inventoried this year and those scheduled for inventory in 1984.

In summary, 31 square miles of land were physically inspected this summer. This represents 269 individual drill holes in the survey. Approximately fifty-one percent of the holes inspected, of 138 holes, were previously capped with concrete caps. In almost all cases these were tested to determine how secure they were in the drill hole and not removed. An attempt was made to remove several concrete caps, but in every case the cap was well secured. Two concrete caps had failed and slipped down the drill hole and were recapped. D. C. Edmiston August 22, 1983

Approximately forty-one percent of the holes, or 111 holes, were recapped with new concrete caps. The old caps were usually permaplugs and in a few cases the old octoplug. These were either removed or breeched, when possible, so that water levels and mud columns could be measured. The old caps were left in the drill hole at a depth of five feet and a new concrete cap was installed at approximately two feet below the surface and backfilled to the surface.

After completing this survey, it was determined that nine drill holes and one from Texasgulf's 1982 inventory required resealing. One drill hole in Section 20, as determined from our October, 1982 inventory, was also inadequately sealed. Appendix E lists those holes resealed. All ten drill holes were resealed in late July using a mixture of water, Shur-gel, and Quick-gel. They were then recapped with concrete caps and backfilled to the surface. Mud specifications exceeded those required by the Wyoming DEQ. A sample of abandonment fluid submitted to NL Industries for testing yielded the following characteristics:

	Actual	Requirement
API filtrate	4.8 cc	13.5 cc
10 Min. Gel Strength	42 lbs./100 ft. <sup>2</sup>	20 1bs./100 ft. <sup>2</sup>

This same type of program will be conducted in 1984 on the remaining Lost Creek/Conoco property. Approximately ten square miles will be covered, containing around 500 drill holes. The 1984 program will be more time consuming since all drill holes will have to be recapped with concrete caps and the extensive number of holes left to be inventoried.

CAT/dd

cc: 03-002-006-04 C. Alan Tapp Page 2

### APPENDICES

Constantine Systems

and the second second

Conception of the second

And a second second

Best of the second seco

Renti-ce and and a second

String of

Construction of the local data

Brought .....

Contraction of the second seco

and a standard and the stand

All the second s

Sector Sector Sector

.

۲.

.

Wyoming, Department of Environmental Quality Notice of Violation	Appendix A
Proposed Remedial Plan, November 24, 1982	Appendix B
Drill Hole Inspection Summary, 1983	Appendix C
Drill Hole Inventory by Section	Appendix D
Summary of Sealed Drill Holes	Appendix E

### APPENDIX A

Wyoming	Department	of	Environmental	Qua	lity
Notice o	of Violatior	1	May	20,	1982

Anti-terretorismon and

and the second s

(and the second second

Constant of Consta

all solutions

Sector and the sector of the s

(magnet-mapping) incom

Super-based (Shidow)

Richard Strange

2

	RE_EIVED1	03-002-006-0
ATE OF WYOMING	MAY 2 4 1982	ED HERSCHLER GOVERNOR
	Tg Proj.Eval Dept. Cpl2pn CC 80404	•
Departmet	nt of Environmental Quality	to Frank
	LAND QUALITY DIVISION Erisman	and Lynn
401 WEST 19TH STREET	TELEPHONE 307-777-7756 graha CHEYEN	5 - 2 6 - 8 2 NE, WYOMING 82002

May 20, 1982

CERTIFIED MAIL RETURN RECEIPT REQUESTED Certified No. 73824

Mr. David C. Edmiston
Vice - President, Special Projects
Texasgulf, Incorporated
5926 McIntyre Street
Golden, Colorado 80401

RE: Notice of Violation, Docket # 1085 - 82, Drilling Notification #47

Dear Mr. Edmiston:

Enclosed you will find an inspection report dated May 10, 1982, recommending a Notice of Violation and the Notice of Violation.

We expect Texasgulf, Inc. to respond to this Notice of Violation by June 18, .1982, by providing a detailed plan for correcting surface capping and sealing problems found during the May 7 - 10, 1982, inspection. A projected timetable should also be provided for completion of remedial work necessary to bring all sites drilled by Texasgulf in Township 24 North, Range 92 West, Township 25 North, Range 92 West, and Township 25 North, Range 93 West, in compliance with Wyoming Statute 35-11-404.

It is hoped this course of action will avoid a recommendation for enforcement action, which would be made after June 18, 1982, depending upon your response.

Should questions arise, please call me at (307) 777-7756.

Sincerely,

Roy<sup>V</sup>G. Spears Abandoned Drill Site Program Supervisor

RGS:mk

Enclosures: Notice of Violation Inspection Report

cc: Alan Guile

HE STATE

#### NOTICE OF VIOLATION

IN THE MATTER OF THE NOTICE ) OF VIOLATION ISSUED TO MR. ) DAVID C. EDMISTON, VICE- ) PRESIDENT, SPECIAL PROJECT ) TEXASGULF INC., 5926 McINTYRE) STREET, GOLDEN, CO 80401 ) Certified No. 73824, DN #47

1

DOCKET NO. 1085-82

#### NOTICE

#### NOTICE IS HEREBY GIVEN THAT:

61

- This notice is being sent to you pursuant to Wyoming Statute 35-11-701(c)(i), which requires that in any case of the failure to correct or remedy an alleged violation, the Director of the Department of Environmental Quality shall cause written notice to be issued and served upon the person alleged to be responsible;
- On May 7 and 10, 1982, an inspection was conducted by a representative of the Land Quality Division, Department of Environmental Quality. Drill sites inspected were located in T.24N., R.92W., T.25N., R.92W., and T.25N., R.93W.;
- 3. Said inspection revealed that Drill Holes Numbered TC17, TG 19 18 25 92, TG 21 18 25 92 and 27 other holes identified in the report of said inspection, were not sealed as required by Wyoming Statute 35-11-404(c)(ii). Wyoming Statute 35-11-404(c)(ii) requires that drill holes which have encountered any ground-water shall be sealed;
- 4. Said inspection also revealed that Drill Holes Numbered TC 17, TG 19 18 25 92, TG 21 18 25 92 and 41 other holes identified in the report, were not properly surface capped. This in in violation of Wyoming Statute 35-11-404(c)(iii).
- With this document, the Department of Environmental Quality is notifying Mr. David C. Edmiston of Texasgulf Inc. of the aforementioned violations.
- 6. Any person who violates any provision of the Environmental Quality Act or any rule, standard, permit, license or variance adopted thereunder is liable to a penalty of ten thousand dollars (\$10,000) for each day of violations, which penalty may be recovered in a civil action brought by the Attorney General in the name of the People of the State of Wyoming.

day of DATED this , 1982.

Roger Shaffer for

Walter C. Ackerman, Administrator Land Quality Division Department of Environmental Quality

PLEASE DIRECT ALL INQUIRIES REGARDING THIS NOTICE OF VIOLATION TO Roy Spears, Abandoned Drill Site Program Supervisor, Department of Environmental Quality, Land Quality Division, 401 West 19th Street, Cheyenne, WY 82002, Telephone (307) 777-6192, OR Alan Guile, Abandoned Drill Site Inspector, 210 Lincoln St., Lander, WY 82520, Telephone (307) 332-3047.

#### INSPECTION REPORT

RE : Texasgulf, Inc. Drilling Notification No. 47

DATE OF TRIP: May 7 and 10, 1982

SUBJECT : Inspection of DN47

PARTICIPANTS: C. Alan Tapp - Texasgulf Alan Guile - Lander DEQ-LQD AS

PREPARED BY : Alan Guile, Abandoned Drill Site Inspector, District II

On May 7 and 10, 1982, an inspection of the above was conducted.

Of the 94 holes reported in 1979, 16 holes or 17% were inspected. Of the 148 holes reported in 1980, 26 holes or 18% were inspected. Surface reclamation was adequate at all sites and therefore is not reported in the summary.

#### Summary of results - 1979

TC 18 NWNE, Section 34, T.25N., R.93W. TD 800 feet No cap. Dry hole. Violation Wyoming Statute 35-11-404(c)(iii)

TC 17 NWNE, Section 34, T.25N., R.93W. TD 800 feet No cap. Encountered water at -163 feet. No bottom at -295 feet. Violation of Wyoming Statute 35-11-404(c)(ii) and (iii).

TT 146 NWNE, Section 24, T.25N., R.93W. TD 700 feet Perma-plug. Water at -192 feet with bridge or bottom at -215 fee $\tilde{\tau}$ . Violation of Wyoming Statute 404(c)(ii) and (iii)

TT 149 NWNE, Section 24, T.25N., R.93W. TD 700 feet Perma-plug. Water at -191 feet with bridge or bottom at -247 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TT 148 NWNE, Section 24, T.25N., R.93W. TD 560 feet Perma-plug. Water at -196 feet with bridge or bottom at -201 feet. Violation of Wyoming Statute 404-(c)(iii).

TT 155 SENW, Section 19, T.25N., R.92W. TD 514 feet Perma-plug. Water at -179 feet with bridge or bottom at -256 feet. Violation of 404(c)(ii) and (iii).

TT 151 SWNW, Section 19, T.25N., R.92W. TD 660 feet Perma-plug. Water at -179 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 19 18 25 92 SESE, Section 18, T.25N., R.92W. TD 465 feet Perma plug. Water at -155 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 13 18 25 92 SESE, Section 18, T.25N., R.92W. TD 500 feet Perma-plug. Water at -154 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 47 20 25 92 NESW, Section 20, T.25N., R.92W. TD 460 feet Perma-plug. Water at -124 feet with bridge or bottom at -156 feet. Violation of Wyoming Statute 404(c)(ii) and (iii). Inspection Report Texasgulf, Inc. Drilling Notification No. 47 May 7 and 10, 1982 Page 2

Part of the second

TG 46 20 25 92 NESW, Section 20, T.25N., R.92W. TD 460 feet Perma-plug. Water at -125 feet with bridge or bottom at -167. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 49 20 25 92 NESW, Section 20, T.25N., R.92W. TD 460 feet Perma-plug. Water at -115 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 7 29 25 92 SESE, Section 29, T.25N., R.92W. TD 600 feet Perma-plug. Unable to check down hole conditions as Perma-plug slid down the hole. Violation of Wyoming Statute 404(c)(iii).

TG 6 29 25 92 SESE, Section 29, T.25N., R.92W. TD 600 feet Perma-plug. Water at -143 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 3 6 24 92 SENW, Section 6, T.24N., R.92W. TD 400 feet Perma-plug. Water at -175 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 2 6 24 92 SENW, Section 6, T. 24N., R. 92W. TD 400 feet Perma-plug. Water at -175 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

Summary of results - 1980

TG 21 18 25 92 SESE, Section 18, T.25N., R.92W. TD 580 feet Perma-plug. Water at -152 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 22 18 25 92 SESE, Section 18, T.25N., R.92W. TD 580 feet Perma-plug. Unable to check down hole as Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

TG 20 18 25 92 SESE, Section 18, T.25N., R.92W. TD 580 feet Perma-plug. Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

TG 19 19 25 92 NENE, Section 19, T.25N., R.92W. TD 580 feet Perma-plug. Water at -159 feet with bridge or bottom at -173 feet. Violation of Wyoming Statute 404(c)(iii).

TG 18 19 25 92 NENE, Section 19, T.25N., R.92W. TD 580 feet. Perma-plug. Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

TG 15 19 25 92 NENE, Section 19, T.25N., R.92W. TD 580 feet. Perma-plug. Perma-plug slid down hole. Violation of Wyoming Statute 404(c)(iii).

/3,001213

Inspection Report Texasgulf, Inc. Drilling Notification No. 47 May 7 and 10, 1982 Page 3

[

TG 53 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -149 feet with bridge or bottom at -163 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 50 17 25 92 SWSW, Section 17, T.25N., R.92W. TD 580 feet Perma-plug. Water at -157 feet with bridge or bottom at -291 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 49 17 25 92 SWSW, Section 17, T.24N., R.92W. TD 580 feet Perma-lug. Water at -151 feet with bridge or bottom at -165 feet. Violation of Wyoming Statute 404(c)(iii).

TG 73 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet. Perma-plug. Water at -150 feet with bridge or bottom at -162 feet. Violation of Wyoming Statute 404(c)(iii).

TG 38 17 25 92 SWSW, Section 17, T.25N., R.92W. TD 580 feet Perma-plug. Water at -150 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 52 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -147 feet with bridge or bottom at -211. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 59 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Perma-plug slid down hole. Violation of Wyomaing Statute 404(c)(iii).

TG 60 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -137 feet with bridge or bottom at -190 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 61 20 25 92 NWNW, Section 20, T.25N., R.92W. TD 580 feet Perma-plug. Water at -147 feet with bridge or bottom at -238. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 37 21 25 92 NWNE, Section 21, T.25N., R.92W. TD 500 feet Unable to locate hole.

TG 41 21 25 92 NWNE, Section 21, T.25N., R.92W. TD 580 feet. Perma-plug. Water at -119 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 4 15 25 92 SESW, Section 15, T.25N., R.92W. TD 400 feet. Perma-plug. Water at -104 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

. ./4

'' 'Inspection Report
 Texasgulf, Inc.
 Drilling Notification No. 47
 May 7 and 10, 1982
 Page 4

TG 5 15 25 92 SESW, Section 15, T.25N., R.92W. TD 400 feet Perma-plug. Water at -91 feet with bridge or bottom at -238 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 3 22 25 92 NENW, Section 22, T.25N., R.92W. TD 580 feet Perma-plug. Water at -99 feet with no bottom at -300 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 4 32 25 92 NENW, Section 32, T.25N., R.92W. TD 260 feet Perma-plug. Water at -135 feet with bottom at -255 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 6 28 25 92 SWNW, Section 28, T.25N., R.92W. TD 340 feet Perma-plug. Water at -81 feet with bridge or bottom at -170 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 7 28 25 92 SWNW, Section 28, T.25N., R.92W. TD 340 feet Perma-plug. Water at -72 feet with bridge or bottom at -196 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 13 29 25 92 SESE, Section 29, T.25N., R.92W. TD 600 feet Perma-plug. Water at -134 feet with bridge or bottom at -187 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 27 6 24 92 NENE, Section 6, T.24N., R.92W. TD 240 feet Perma-plug. Water at -94 feet with bottom at -220 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

TG 25 6 24 92 NENE, Section 6, T.24N., R.92W. TD 240 feet. Perma-plug. Water at -125 feet with bottom at -223 feet. Violation of Wyoming Statute 404(c)(ii) and (iii).

#### Conclusions .

Of the 42 holes inspected 41 (98%) had capping violations. The other hole was not located. Of the 35 holes in which down hole conditions were checked, 30 (86%) were in violation of sealing requirements.

It is recommended that a Notice of Violation be issued.

#### AG:tc

cc: -Roy Spears, Abandoned Drill Site Program Supervisor - Cheyenne DEQ-LQD
-C. Alan Tapp, Senior Geologist
Project Evaluation Department
Texasgulf Inc.
5926 McIntyre Street
Golden, CO 80401

### APPENDIX B

And and a second s

Annound Street

Supervision of the second seco

Rent La

Berner . . .

Proposed Remedial Plan

November 24, 1982

# Texasgulf Inc.

5926 McIntyre Street Golden, Colorado 80403 (303) 279-2636

Project Evaluation Department November 24, 1982

Department of Environmental Quality Land Quality Division 401 West 19th Street Cheyenne, Wyoming 82002

Attention: Mr. Roy Spears

Dear Mr. Spears:

On October 14, 1982, Texasgulf initiated a field program to inventory abandoned drill holes in Section 20, Township 25 North, Range 93 West of Sweetwater County, Wyoming. The inventory consisted of vegetation surveys in and around the drill sites and measurements of water levels and mud column depths for each hole. Seventy-nine drill holes were inventoried during the process, which was completed on October 22, 1982. The data generated by the inventory and Texasgulf's interpretation are enclosed. Our interpretations indicate that all holes exhibit statistical adequacy for reclamation, all holes are capped, and all holes were sealed according to D.E.Q. regulations which were in effect at the time they were drilled.

Results of studies by Texasgulf and a hydrologic consultant support the fact that on the Lost Creek/ Conoco property the Battlesprings Formation is one aquifer. A potentiometric map can be constructed for Section 20. This map depicts a relatively uniform water table which fits well with local and regional data, regardless of mud levels in drill holes.

An independent hydrologic evaluation of Texasgulf's raw drill hole data plus other sources of data was made by Hydro-Search, Inc. and is enclosed. Their final interpretation is that the Battlesprings Formation is one aquifer. In light of the compiled facts it is difficult to make any other interpretation.

As a result of local physical conditions present in each bore hole after sealing, drilling mud levels are subject to change. One drill hole inspected in Section 20, Tg-35-20, did not meet Texasgulf's sealing standards. This hole will be resealed in conjunction with the 1983 program. Texasgull Inc.

Department of Environmental Quality November 24, 1982

Page 2

Texasgulf's Lost Creek/Conoco property consists of approximately forty sections of land. Since our inventory covered only one section of our property, we cannot be certain other areas will show identical results. We will inventory other holes on our property in 1983 and make necessary corrections to bring any substandard findings to our standards. We will initiate the program outlined below during May of 1983 to cover about half of our property, or twenty sections. In 1984 the remainder of the property will be inventoried in the same manner.

- Beginning in May, 1983, Texasgulf will inspect about twenty sections in the Lost Creek/Conoco property in the same manner as performed in Section 20. The D.E.Q. will be provided the inventoried data.
- (2) Concrete caps will be installed in all inventoried holes in accordance with D.E.Q.'s recommendations.
- (3) During the inventory each drill site will be evaluated for reclamation success. Any found substandard will be reseeded in accordance to Wyoming Statute 35-11-404(c)(v).
- (4) Drill holes which we locate that do not meet drill holes abandonment standards will be identified and resealed at the end of the summer inspection program.

Sincerely,

C. Man Japp

C. Alan Tapp Project Manager

CAT/dd

Enclosures

cc: D. C. Edmiston Lynn Graham 03-002-006-04

### APPENDIX C

Partition and services

Strengt'

Common and a second

20 men

And a second

Research to the second

÷,

Drill Hole Inspection Summary, 1983

				No. Holes <sub>l</sub> Inspected	No. Dry Holes	No. Holes w/Concrete Cap	No. Holes s Recapped
Sec.	5, Tá	24N,	R9.2W	12	0	10	2
Sec.	6			32	9	7	25
Sec.	], T	24N,	R93W	1	1	0	1
Sec.	2, T	25N,	R91W	2	1	0	1
Sec.	2, T	25N,	R92W	6	1	3	2
Sec.	3			15	0	12	3
Sec.	4			4	0	4	0
Sec.	5			5	1	4	. 1
Sec.	8			3	0	1	2
Sec.	10			1	0	0	1
Sec.	11			15	2	9	6
Sec.	14			7	0	0	7
Sec.	15			1	0	Ó	1
Sec.	28			23	1	13	8
Sec.	29			26	0	7	17
Sec.	30			2	0	2	0
Sec.	31			20	0	17	3
Sec.	32			22	0	14	8
Sec.	33			29	0	25	<sup>7</sup>
Sec.	36			8	0	8	3
Sec.	16,	T26N,	R91W	14	3	2	7
Sec.	21,	T26N,	R92W	9	1	0	5
Sec.	24,	T26N,	R92W	3	0	0	2
Sec.	25			. 3	0	0	3
Sec.	29			3	1	0	1
Sec.	36			_3_	_0_	0	1
	То	tals		269	21	138	111

.

Some drill sites were inspected but the actual drill hole was not locatable. Not all holes insepcted were Texasgulf's.

Support Stranger 014 consecution of the ----provident (processor) Real Service

### APPENDIX D

and a constraints

Drill Hole Inventory by Section

Page 1 of 19

:

.

	r				
<u>Hole ID</u>	Location	<u>Original Cap</u>	<u>Depth</u> Water	<u>to</u> Mud	Recapped w/concrete
		Sec. 5,T24N,R92W		<b>;</b>	-
Tg 5-5	Sec. 5-24W-92W	Concrete Did not remove		:	
Tg 2-5	Sec. 5-24W-92W	Concrete Did not remove		,	
Tg 3-5	Sec. 5-24N-92W	Concrete Did not remove			•
Tg 4-5	Sec. 5-24N-92W	Concrete Did not remove			
Tg 6-5	Sec. 5-24W-92W	Concrete Did not remove			
Tg 11-5	Sec. 5-24N-92W	Concrete Did not remove			
Tg 1-5	Sec. 5-24N-92W	Perma-plug	185 <b>'</b>	203'	Yes
Tg 9-5	Sec. 5-24N-92W	Concrete on surface but could not locate hole			
 Tg 10-5	Sec. 5-24N-92W	Octoplug			Yes
Tg 12-5	Sec. 5-24N-92W	Concrete cap surface Did not remove			
Tg 8-5	Sec. 5-24N-92W	Concrete cap Did not remove			
Tg 7-5	Sec. 5-24N-92W	Concrete cap Did not remove			
		<u>Sec. 6-T24W,R92W</u>			·
Tg 9-32	Sec. 32-25N-92W	Concrete Did not remove			
Tg 8-32	Sec. 32-25N-92W	Octoplug	197'	238'	Yes
Tg hole approx. of Tg 20-29. So removed stake!	200' due north meone has	Concrete cap Did not remove			
Tg 27-6	Sec. 6-24N-92W	Perma-plug	115'	219'	Yes

physical sectors of the sector sector

Provide

Provide a

· power,

Approximation of the second se

and the second

Manual Andrewson

and the second

Second Street and Advances

Barrow .

provention of the second

Second Second

Manager Contraction of the second sec

Second Second

arrend .

Strategic Control of Strategics

Page 2 of 19

•

					Disamut
Hole ID	Location	<u>Original Cap</u>	<u>Depth</u> Water	Mud	Recapped w/concrete
Tg 36-6	Sec. 6-24N-92W	2 Octoplugs	Dry	:	Yes -
Tg 6-6	Sec. 6-24N-92W	Perma-plug	185'	348'	Yes
Tg 35-6	Sec. 6-24N-92W	Concrete cap Did not remove			
Tg 17-6	Sec. 6-24N-92W	Perma-plug	Dry	1	Yes
Tg 16-6	Sec. 6-24N-92W		Dry		Yes
Tg 33-6	Sec. 6-24N-92W	Concrete cap @+3' Did not remove			
Tg 34-6	Sec. 6-24N-92W	Concrete was around collar of hole. How- ever, pushed bar dow +5' and could not hi cement cap.	<i>i</i> n		·
Tg 15-6	Sec. 6-24N-92W	Perma-plug	Dry		Yes
Tg 14-6	Sec. 6-24N-92W	Perma-plug	180'	182'	Yes
Tg 13-6	Sec. 6-24N-92W	Perma-plug	Dry		Yes
Tg 11-6	Sec. 6-24N-92W	Perma-plug	181'	281'	Yes
Tg 12-6	Sec. 6-24N-92W	Perma-plug	219'	349'	Yes
Unmarked	Sec. 6-24N-92W	· ·	Dry		Yes
Tg 31-6	Sec. 6-24N-92W	Concrete Did not open			
Tg 30-6	Sec. 6-24N-92W	Concrete Did not open			
Unmarked, stake removed	East of Tg 30-6		Dry		Yes
Unmarked, stake removed	Sec. 6-24N-92W North of Tg 31-6	Concrete Did not open			
Unmarked, stake removed	Sec. 6-24N-92W northwest of hole above.	Perma-plug	Dry		Yes

Converted of

groups and

Borne and

Sayan and

Banand,

BNDIAL STREET

Shifting the second sec

(Belling)

pictore,

and the second

Elliphings Angeneti

Rid and a

Ŀ,

.

, ř	<u>Hole ID</u>	<u>Location</u>	<u>Original Cap</u> Sec. 6,T24N-R92W	<u>Depth 1</u> Water	to Mud	Recapp w/concr	
	Tg 25-6	Sec. 6-24N-92W	Perma-plug	125'	214'	Yes	
	Tg 20-6	Sec. 6-24N-92W	Perma-plug	122'	174'	Yes	
	Tg 8-6	Sec. 6-24N-92W	Perma-plug	199'	341'	Yes	
÷.,	Tg 7-6	Sec. 6-24N-92W	Perma-plug	228'?	355'	Yes	
	Tg 9-6	Sec. 6-24N-92W	Perma-plug	192'	212'	Yes	
	Tg 23-6	Sec. 6-24N-92W	Perma-plug	85'?	225'	Yes	
	Tg 24-6	Sec. 6-24N-92W	Perma-plug	?	113'	Yes	
	Tg 22-6	Sec. 6-24N-92W	Perma-plug	200'	209'	Yes	
	Tg 21-6	Sec. 6-24N-92W	Perma-plug	194'	232'	Yes	
	Tg 5-6	Sec. 6-24N-92W		Dry		Yes	
***			Sec. 1,T24N,R92W				
	Tg 1-1 This hole has not been re- claimed	Sec. 1-24N-92W	Perma-plug	Dry	Mud pit is still open		
	Claimed						
			Sec. 2,T24N,R92W				
	Open Hole - No ID. Probably an old Conoco hole. Due south of SW section corner Sec. 36 approx. 40'. Tried to recap but hole was too large.						
	RD-464		0pen	Dry		Yes	
			Sec. 2, T25N-R92W				
	Tg 2-2	Sec. 2-25N-92W	Perma-plug	157'	307'	Yes	
	Tg 6-2	Sec. 2-25N-92W	Concrete Did not disturb				

l Sell

Ļ

### Page 4 of 19

:

					•
Hole ID	Location	<u>Original Cap</u>	<u>Depth</u> Water	to Mud	Recapped w/concrete
Tg 7-2	Sec. 2-25N-92W	Concrete to surface Did not disturb	Ž	•	
Tg 5-2	Sec. 2-25N-92W	Concrete Did not disturb			•
Tg 4-2	Sec. 2-25N-92W		Dry		Yes
Tg 8-2	Sec. 2-25N-92W	Couldn't find hole			
		Sec. 3,T25N,R92W			
Tg 7-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 5-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 6-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 8-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 14-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 1-3	Sec. 3-25N-92W	Perma-plug Cap slipped and cou not breach to measu water.			Yes
TG 13-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 12-3	Sec. 3-25N-92W	Concrete cap Did not remove			
Old unmarked ho E-W fence toward	le north of Tg's d western end	Open			Yes
Tg 3-3	Sec. 3-25N-92W	Concrete cap Did not remove			
Tg 4-3	Sec. 3-25N-92W	Concrete Did not remove			
Tg 2-3	Sec. 3-25N-92W	Cannot locate drill hole. Marker knocke down.			

•

.

Contraction of the second

Alexandra Alexandra Alexandra Alexandra Alexandra

(Constant)

Annual Contraction

diversion of the second second

Annual Contraction

Constant of the second se

All Company

.

diponer,

Contraction of the second

Compared a

distance of the second

Concession of the second secon

Second and a second sec

# Page 5 of 19

				Depth to	Recap
	Hole ID	Location	Original Cap	Water Mud	w/conc
	Tg 11-3	Sec. 3-25N-92W	Concrete cap Could not get through it. It was badly broken.	•	Yes
	Tg 10-3	Sec. 3-25N-92W	Concrete cap down approx. 3'. Could not remove it.	3	
<u>a</u>	Tg 9-3	Sec. 3-25N-92W	Concrete cap Did not remove it. Cap down +4'.		
	*	<u>S</u>	ec. 4,T25N,R92W		
	Tg 1-4	Sec. 4-25N-92W	Concrete cap @ 3'. Did not remove.		
	Tg 2-4	Sec. 4-25N-92W	Concrete cap @ appro 3'. Did not remove.	ox.	
٨.,	Tg 3-4	Sec. 4-25N-92W	Concrete tap @ appro 3'. Did not remove.	ox.	
4	Tg 4-4	Sec. 4-25N-92W	Concrete cap @ appr +4'. Did not remove		
		5	Sec. 5, T25N, R92W		
	Tg 3-5	Sec. 5-25N-92W	Concrete cap Did not remove		
	Unidentified hol Could not locate	le between Tg 3-5 a e hole.	and Tg 2-5		
	Tg 2-5	Sec. 5-25N-92W	Concrete cap Did not remove. Cap @ approx. 3'		
	Tg 1-5	Sec. 5-25N-92W	Concrete cap at surface. Removed an found 2' dirt on to of sage.bush. Recap	p	Yes
	Tg 13-5	Sec. 5-25N-92W	Concrete Did not remove		

-

-

.

12

- 4

ŝ	Hole ID	Location	Original Cap	<u>Depth t</u> Water	o Mud	Recap w/conc
		Se	c. 8,T25N,R92W	•	•*	
	Tg 1-8	Sec. 8-25N-92W	Concrete cap to surface. Good cap did not remove.	4		
	Capped unidentificentral part of S	ied open hole near Section 8.	1 x x 2 x			Yes
	Unreclaimed, unio drill hole in SE <sup>3</sup>		Open but dry - Capped but did not fill.			Yes
		Se	c. 10,T25N-R92W			
	Conoco Hole in Ni	E¼ SE¼ Sec. 10	Open Recapped			Yes
		Se	c. 11,T25N,R92W	×	3	•
	Tg 5-11	Sec. 11-25N-92W	Concrete cap Did not remove			
	Tg 1-11	Sec. 11-25N-92W	Perma-plug	Water just on top of mud.	86 '	Yes
	Tg 9-11	Sec. 11-25N-92W	Concrete cap Did not remove			
	Tg 6-11	Sec. 11-25N-92W	Concrete cap @ approx. 3'. Did not remove.			
	Tg 7-11	Sec. 11-25N-92W	Concrete cap @ approx. 4'. Did not remove.			
	Tg 10-11	Sec. 11-25N-92W	Concrete cap Did not remove			
	Tg 2-11	Sec. 11-25N-92W	Perma-plug	123'	308'	Y
	Tg 11-11	Sec. 11-25N-92W	Concrete cap Did not remove			
	Tg 3-11	Sec. 11-25N-92W	Perma-plug	119'	213'	`

ŝ

Page 7 of 19

				Page /	OT 19	
	Hole ID	Location	Original Cap	<u>Depth</u> Water	the second s	Recapped
	note in		Uriginal cap	water	Mud	w/concrete
	Tg 8-11	Sec. 11-25N-92W	Concrete cap Did not remove		•	-
	Hole # 673	Sec. 11	Open hole	Dry		Yes
	Hole #109	Sec. 11	Open hole	Dry		Yes
	Tg 12-11	Sec. 11-25N-92W	Concrete cap @ approx. 3'. Did not remove.		•	
	Tg 13-11	Sec. 11-25N-92W	Concrete cap just under surface. Did not remove.			
	Tg 4-11	Sec. 11-25N-92W	Perma-plug	119'	244'	Yes
		Sec	c. 14,T25N,R92W			
	Tg 6-14	Sec. 14-25N-92W	Perma-plug	128'	333'	Yes
	Tg 7-14	Sec. 14-25N-92W	Perma-plug	132'	354'	Yes
	Tg 5-14	Sec. 14-25N-92W	Perma-plug	119'	340'	Yes
	Tg 4-14	Sec. 14-25N-92W	Perma-plug	121'	354'	Yes
•	Tg 3-14	Sec. 14-25N-92W	Perma-plug	122'	353 5	Yes
٢	Tg 2-14	Sec. 14-25N-92W(?)	Perma-plug	137'	357'	Yes
	Tg 2-14	Sec. 14-25N-92@(?) NNW approx. 400' from above hole 539200-760000	Perma-plug	125'	348'	Yes
		Sec	2. 15,T25NR92W		-	
	Old Conoco hole	- NE¼ Sec. 15	Open hole			Yes
		Sec	28,T25N,92W			
	Stake has been r NE of northern e more or less 400	nd of last fence	Concrete cap Did not remove			
		emoved. Hole is e hole 200' more	Concrete cap Did not remove			

Starren)

Second Second

Sectors,

Richardson and American Street Street

All states of the second state

Contraction of the second seco

Eliferative Constant of the second se

Second Se

Contrast of the second se

Brinne, Status Brigadi

and the second

Province of the second se

Colorado -

### Page 8 of 19

٠.

١

Hole ID	Location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
Tg (?) Part of label is missing. Due north of above hole.	Sec. 28-25N-92W	Perma-plug	125'	131 <sup>-1.</sup>	Yes
Tg 16-28	Sec. 28-25N-92W	Concrete Did not remove			
Tg 19-28	Sec. 28-25N-92W	Concrete Did not remove			
Label missing. H due south of Tg	lole approx. 400' 19-28	Concrete Did not remove			
Tg 17-28	Sec. 28-25N-92W	Concrete Did not remove	•		
Tg 22-28	Sec. 28-25N-92W	Concrete Did not remove			
Tg 6-28	Sec. 28-25N-92W	Perma-plug	83'	164'	Yes
Tg 7-28	Sec. 28-25N-92W	Perma-plug	71'	171'	Yes
from east from T	200' more or less g 7-28-25-92. Could Stake was knocked				
Label missing NE坛	Sec. 28-25N-92W	Perma-plug	71'	233'	Yes
Tg 10-28	Sec. 28-25N-92W	Concrete Did not remove			
Tg 11-28	Sec. 28-25N-92W	Concrete cap Did not remove			
Tg 12-28	Sec. 28-25N-92W	Concrete Did not remove			
Tg 1-28	Sec. 28-25N-92W	Perma-plug	133'	311	Yes
Label missing. H 400' easterly fr	lole more or less rom Tg 1-28.	Perma-plug	138'	173'	Yes
Label missing. H 400' easterly fr	Hole more or less rom Tg 7-28	Perma-plug	138'	275'	Yes

Contraction of the local diversion of the loc

Real Procession of the Process

Spolences and spolences

Parameter

percent,

Restoration of the second

The second second

100000

ane cod

Contraction of the second

And the second s

Support Learning

Page 9 of 19

•

						•
	<u>Hole ID</u>	Location	<u>Original Cap</u>	<u>Depth</u> Water	to Mud	Recapped w/concrete
	Tg 15-28	Sec. 28-25N-92W	Concrete Did not remove		•	
	Tg 3-28	Sec. 28-25N-92W	Hole open @ surface. Perma-plug was side- ways.			Yes
	Stake missing. D Tg 3-28. More or		Concrete cap Did not remove			
	Site more or less above hole. Does have been drille	not appear to	· · ·			
	Tg 13-28	Sec. 28-25N-92W	Concrete cap Did not remove			
		2	Sec. 29,T25N,R92W			
	Tg 3-29	Sec. 29-25N-92W	Perma-plug Slipped down hole	140'	323'	Yes
	Tg 5-29	Sec. 29-25N-92W	Perma-plug Slipped down hole	Could not		Yes
				measure water.		
•••	Tg 4-29	Sec. 29-25N-92W	Perma-plug	154'	282'	Yes
	Tg 2-29	Sec. 29-25N-92W	Perma-plug	155'	247'	Yes
	Tg 10-29	Sec. 29-25N-92W	Perma-plug	154'	170'	Yes
	Tg 9-29	Sec. 29-25N-92W	Perma-plug	150'	312'	Yes
	Tg 7-29	Sec. 29-25N-92W	Could not locate hole.			
	Number is unknow hole approx. 200 Tg 7-29		Cap slid down hole			Yes
	Unmarked Tg hole south of Tg 7-29	approx. 400-500'	Perma-plug	135'	311'	Yes
·	Tg 20-29 (Someone has pulled up our drill hole stake this year)	Sec. 29-25N-92W	Cement cap Did not remove			Yes

- And a second

processo bases

Annual I

Course of Course

Approved a

Concernant Concernant

dimension of the second

And the second s

Second and

And the second sec

Board . . . . .

Altrophy and a second

Second Second

Resolution of the second

### Page 10 of 19

•

					Derth	1 -	D
	Hole ID	Loca	tion	<u>Original Cap</u>	<u>Depth</u> Water	Mud	Recapped w/concrete
	Tg 20-29	Sec.	29-25N-92W	Concrete cap Did not remove		• • •	• .
	Due north of abo been removed.	ve ho	le. Stake has	Concrete Did not remove	,		
	Tg 27-29	Sec.	29-25N-92W	Concrete Cap had slipped down hole 5' more or less Repositioned and fil back up w/dirt. Did remove.	led		
	Tg 28-29	Sec.	29-25N-92W	Concrete cap @ surfa Did not remove	ce		
	Stake has been removed & does not have ID. Hol is SW of Tg 1-29			Perma-plug	132'	157'	Yes
	Tg 1-29	Sec.	29-25N-92W	Perma-plug	142'	216'	Yes
	Tg 8-29	Sec.	29-25N-92W	Perma-plug	143'	177'	Yes
• .	Tg 19-29	Sec.	29-25N-92W	Octoplug w/"stuff" on top. Could not remove-slipped down hole.			•
	Tg 18-29	Sec.	29-25N-92W	Could not locate cap @ +5', no evidence of cement.			Yes
	Hole WSW from Tg 18-29. Label missing.		•	Perma-plug	105'	332'	Yes
	South of above h less. No stake.	ole 2	00' more or	Octoplug	102'	330'	Yes
	Tg 16-29	200'	29-25N-92W more or less above hole.	Could not locate cap @ +5'. Cap appeared to be in solid.			
	Tg 15-29	Sec.	29-25N-92W	Could not locate cap @ +5'. Solid cap.			

GUITTER, phone of Constraint of Co All Transport to a constant Part of the second Turning and the second

District of the second second

darapeter second

(Same)

Contract of Contra

A CONTRACT OF

### Page 11 of 19

. .

Hole ID	Location	Original Cap	Depth toRecappedWaterMudw/concrete
Tg 23-29	Sec. 29-25N-92W	Concrete Did not remove	· · · · ·
Tg 22-29	Sec. 29-25N-92W	Concrete cap @ +5' Did not remove	
Tg 24-29	Sec. 29-25N-92W	Concrete cap had failed.	127' 181' Yes
Tg 25-29	Sec. 29-25W-92W	Concrete Did not remove	
Tg 26-29	Sec. 29-25N-92W	Concrete Did not remove	
	Se	ec. 31,T25N,R92W	
Tg 3-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 4-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 2-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 22-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 6-31	Sec. 31-25N-92W	Concrete cap Did not remove	* 
Tg 5-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 11-31	Sec. 31-25N-92W	Concrete cap Tried to remove but could not.	
Tg 17-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 7-31	Sec. 31-25N-92W	Concrete cap Did not remove	
Tg 12-31	Sec. 31-25N-92W	Concrete cap Tried to remove but could not	

and the second

And the second s

apressed the second

State of the second

and the second s

gent berng

Report P

personal second

Contraction of the second seco

Neerpot<sup>2</sup>

(investigation of the second s

Manager .

distant of the second sec

pitrose energy

Page 12 of 19

:

	Hole ID	Location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
	Tg31 Hole ID was partially missing	Sec. 31-25N-92W	Perma-plug	141'	184	Yes
		f Tg 12-31-25-92 . Marker has been crete cap. No ID.	Concrete cap Did not remove			
	Marker stake has east of hole Tg approx. +3'.	been removed. Due 11-31-25-92(?)	Concrete Did not remove			
	No ID on hole sta removed. Due wes		Cement cap @ +2' Did not remove			
		Se	c. 30,T25N,R92W			х. - С
	Tg 1-30	Sec. 30-25N-92W	Concrete cap Did not remove			
	No hole marker. S removed. Due eas	Stake has been t from last hole.	Concrete cap @ approx. 3-4'. Did not remove.			· .
		Se	c. 31,T25N-R92W			
•	Tg 15-31	Sec. 31-25N-92W	Concrete cap Cap is +3' thick. Tried to remove but could not.			
	Tg+31 Due south approx 400' from last hole. Stake has been removed. Old lathe by hole Tg 14-31-92.		Octoplug @ +5' Could not breach it to measure for water	•	·	Yes
	Unmarked hole. Si removed. Due sout hole in Sec. #6,	th of NE most	Perma-plug	123'	210'	Yes
	Due west of last stake has been re stake in hole - 1	emoved. (Small	Concrete cap Did not remove			
	Approx. NNE 200' Stake has been re		Concrete cap			

Concernant of the second

gan en al

Berne Contraction

Served in service and

in the second se

and the second sec

-

,

Second and

Provide and the second se

Alternation of the second

Contraction of the second

and the second s

Page 13 of 19

:

Hole ID	Location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
Tg 20-31(?)	Sec. 31 or 30(?) 24N-92W	Concretē cap			
Tg 4-32	Sec. 32-25N-92W	Perma-plug slipped down hole. Could not probe.			Yes
Tg 12-25	Sec25N-92W (Missing sec. No Due to south of #5 200' more or less)	Concrete Did not remove			
Tg 13-25	Sec25N-92W (Missing sec. No Due north of Tg 4-32 200' more or less)	Concrete Did not remove			
Hole on west- central edge of Sec. 32. Label is missing.	Sec. 32-25N-92W	Perma-plug	146'	189'	Yes
Tg 11-32	Sec. 32-25N-92W	Concrete Did not remove			
	Sec. 32;1	[25N-R92W]			
Tg 7-32	Sec. 32-25N-92W	Concrete Did not remove			
Tg 10-32	Sec. 32-25N-92W	Octoplug	129'	228'	Yes
Tg 9-32	Sec. 32-25N-92W	Concrete Did not remove			
Tg 8-32	Sec. 32-25N-92W	Concrete Did not remove			
Tg 1-32	Sec. 32-25N-92W	Perma-plug	203'	254'	Yes
Old Tg hole label is missing	Sec. 32-25N-92W (North central)	Perma-plug	144'	224'	Yes
Tg 18-32	Sec. 32-25N-92W	Concrete Did not remove			

-

Peril

piperet.

alternation of the second

· Particular

Statistics

All and a second s

Personal and a second s

- America

All and a second second

Scores .

and cost

denver denver

Protocol Contraction of the second se

### Page 14 of 19

:

				·			
	<u>Hole ID</u>	Locat	tion	<u>Original Cap</u>	<u>Depth</u> Water	to Mud	Recapped w/concrete
-	Tg 19-32	Sec.	32-25N-92W	Concrete Did not remove		:	
	Tg 5-32	Sec.	32-25N-92W	Perma-plug	153'	294	Yes
	Tg 5-32 (SW 400')Stake has been removed.		32-25N-92W	Concrete Did not remove			
	Tg 14-32 (Due north of above hole)	Sec.	32-25N-92W	Concrete Did not remove			
	Due north of above hole. Stake has been removed.	Sec.	32-25N-92W	Concrete Did not remove	· .		
	Due north of above hole. Tg 17-32	Sec.	32-25N-92W	Concrete Did not remove			
	Tg 2-32	Sec.	32-25N-92W	Perma-plug	150'	215'	Yes
	Tg 4-32	(200' due n above	32-25N-92W(?) more or less orth of the hole & 400' orth of Tg 20)		134'	249'	Yes
			Sec	2. 33,T25N-R92W		· .	
	Tg 15-33	Sec.	33-25N-92W	Concrete Did not remove			
	Tg 16-33	Sec.	33-25N-92W	Concrete Did not remove			
	Tg 4-33	Sec.	33-25N-92W	Concrete Did not remove			
	Tg 3-33	Sec.	33-25N-92W	Concrete Did not remove			
	Tg 2-33	Sec.	33-25N-92W	Concrete Did not remove			
	Tg 1-33	Sec.	33-25N-92W	Perma-plug	169'	216'	Yes
	Tg 5-33	Sec.	33-25N-92W	Concrete Did not remove	,		

and the second second

Barrens .

Apartment 

Resident of the second

directory of the second

Second Contract

.

All and a second se

And a state of the state of the

Rayanton constraints

### Page 15 of 19

				Page 15 of 19	•
	Hole ID	Location	<u>Original Cap</u>	<u>Depth to</u> Water <u>Mud</u>	Recapped w/concrete
	Tg 26-33	Sec. 33-25N-92W	Concrete Did not remove	 	
4	Tg 27-33	Sec. 33-25N-92W	Concrete Did not remove		
	Stake is missing three in central		Concrete Did not remove		
	Tg 24-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 22-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 7-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 6-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 17-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg's(?) No marken a Tg hole. Diffen				
• .	Tg 29-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 20-33	Sec. 33-25N-92W	Concrete Did not remove	•	
	Tg 19-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 18-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 17-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 8-33	Sec. 33-25N-92W	Concrete Did not remove		
	Tg 9-33 Stake was pulled up and lying on ground. Could not locate hole.	Sec. 33-25N-92W			

- Andrew Constant

And States

Services

Super-

A second second

Tripped Cip.

Record

A second

All handled

And the second s

States of the second se

All and a second

difference of

and the second

Announce of the second

Brotug Gardenoversion

Page 16 of 19

. .

				D ! !		
	Hole ID	Location	<u>Original Cap</u>	<u>Depth</u> Water	<u>Mud</u>	Recapped w/concrete
	Hole approx. 200 Stake has been re		Concrete Did not remo <b>ve</b>	<del>.</del>	,	
	Tg 11-33	Sec. 33-25N-92W	Concrete Did not remove		•	
	Tg 12-33	Sec. 33-25N-92W	Concrete Did not remove	•		
	Tg 13-33	Sec. 33-25N-92W	Concrete Did not remove			
	No ID. Stake has Hole is east of		Concrete Did not remove			
	Tg 21-33	Sec. 33-25N-92W	Concrete cap Did not remove			
		Sec	c. 36,T25N,R92W			
	Ţg 6-36	Sec. 36-25N-93W	Concrete cap Did not remove			
•.	Tg 3-36	Sec. 36-25N-93W	Concrete cap Did not remove. Coul not locate cap at 5' Cement around edges hole and @ collars. a second concrete ca	of Put		
	Tg 2-36	Sec. 36-25N-92W	Concrete Did not remove		Ϋ́	
	Tg 1-36	Sec. 36-25N-92W	Concrete Did not remove			
	Tg 4-36	Sec. 36-25N-93W(?)	Concrete Did not remove			
	Tg 8-36	Sec. 36-25N-92W(?) Dug up and no cap present-even though concrete was around collar.	Concrete cap?	99'	191'	Yes
			Octoplug approx. 2-3' down hole. It was turned sideways.			

Contract of Contra

and the second

Space of the second sec

Statement of the second

and the man

(interest)

and the second sec

Street,

And the second s

Reference of the second second

## Page 17 of 19

•

•

•

(Servery)

dimmental second

distant of the second

distantly in the second

dimension of

and the second sec

Service and a service of the second service of the second se

(Korris,

distriction of the second of t

Philipping and a second s

and a second sec

Ereney Ereney

Contraction of the second

			· ·			•
	<u>Hole ID</u>	Location	Original Cap	<u>Depth</u> Water	to Mud	Recapped w/concrete
	Tg 5-36	Sec. 36-25N-92W	Concrete cap Tried to remove but could not. At least 18" thick-maybe more	•		Yes
	Tg 7-36	Sec. 36-25N-92W	Concrete cap to surface. Did not remove.			
		Se	c. 16,T26N,R91W			
	Hole on southern endline @ sur- face.	Sec. 16-26N-91W	Concrete at surface Did not remove cap.			
		from above hole.	Capped-Not Tg hole			
	SW from stock po Draw-old Conoco I not find hole.					
	Due south from al	bove hole. No ID.	Recapped	Dry		
	Due south stock   small hill. Did i		Concrete			
•••	South of above he	ole - Conoco's (B-6	7)			
	B-1115, south of (Conodo's)	above hole	Recapped	Dry		Yes
	South of B-115 a (B-83) Conoco's	pprox. 100' (?)	Octoplug Opened recapped			Yes
	B-112 - South of	B-83	Open	Dry		Yes
		B-9. Could not loca nd it approx. 4' d ould.		• •		Yes
	Hole south of abo	ove hole - No ID	Open			Yes
		ce next to diagonal most hole - no ID -				
	South of above he Left alone.	ole #75/30. Could n	ot move stake.			
	South of #26. #76	6/30. Recapped hole				

Page 18 of 19

1		2 · · ·				*
1	Hole ID Location	Original Cap	51	<u>Depth</u> Water	to Mud	Recapped w/concrete
inal.	Se	c. 21,T26N,R92W				
	D-73 Sec. 21-26N-92W Conoco hole(?)		ŝ.	Dry		Yes
]	Unidentified hole on west edge of S	ec. 21	×	Open, water?		Yes
	Due west of above hole in Osborne D Could not locate holes (2) and not				3	
	Due north of above hole (in a fence Could not locate hole.	N-S)				
	In fence north from above hole. Bot open and old - not Tg's.	h were				Yes
	North of above and next to road. Co locate hole - not Tg's.	uld not				
	West of above hole - not Tg's. Completed Section 21					Yes
	An old Conoco hole next to 1/4 sect for Sections 20 & 21.	ion marker				Yes
	Due north approx. 300' from the abo Not Tg's and already capped	ove hole -				
	Se	c. 24,T26N,R92W			1	
	Unidentified hole next to creek. A mile north of Tg holes. Hlle caved diameter approx. 8-10' deep. Tried couldn't - left open.	3-4' in				
	Unidentified hole in NE/1/4 of Sec.	24 - Open				Yes
	Open hole due west of above hole.					Yes
	Note: Numerous old Conoco holes wer	re checked in Sec.	24.	In most	t cases w	e could

here

17

0

Note: Numerous old Conoco holes were checked in Sec. 24. In most cases we could not locate holes. If they were capped, we left them along. If they were open, we recapped them with concrete.

### Page 19 of 19

Dry

Hole ID	Location	<u>Original Cap</u>	<u>Depth</u> Water	to Mud	Recapped w/concrete	
	Sec	. 25,T26N-R92W			× * •	
Tg 2-25	Sec25-26N-92W	Perma-plug	154'	378'	Yes	
Tg 3-25	Sec. 25-26N-92W	Perma-plug slid down			Yes	
Tg 1-25	Sec. 25-26N-92W	Perma-plug	193' Hit hea fluid @ approx. 200'.		Yes	
			200 .			

### Sec. 29, T26N, R92W

Tg 132-29 Sec. 29-26N-92W

Due north of hole Tg 132-29 approx. 400'. Could not locate hole.

Due north of #20 approx. 600'. Could not locate hole.

### Sec. 36, T26N, R92W

RD 368

1 ....

2

### Open Recapped w/concrete

Checked numerous old Conoco holes. No Tg holes. Recapped any open holes.

Open hole - no ID in south central Sec. 36. Too large to fill. Open approx. 3' in diameter + approx. 6' deep. Not Tg's.

Yes

Yes

### APPENDIX E

Sealed Drill Holes and Abandonment Fluid Characteristics

## Resealed Drill Holes

## HOLE ID

Provent

and the second s

Contraction of the second

and the second second

Tg-35-20-25-92
Tg-1-14-25-92(?)
Tg-2-14-25-92
Tg-3-14-25-92
Tg-4-14-25-92
Tg-5-14-25-92
Tg-7-14-25-92
Tg-13-29-25-92(?)
Tg-14-29-25-92(?)
Tg-2-25-26-92

## LOCATION

NE¼,	NE¼,	Sec.	20,	T25N,	R92W
N₩¼,	NW14,	Sec.	14,	T25N,	R92W
NW14,	NW⅓,	Sec.	14,	T25N,	R92W
N₩¼,	NW14,	Sec.	14,	T25N,	R92W
NW14,	N₩¼,	Sec.	.14,	T25N,	R92W
₩ <sup>1</sup> 4,	NW14,	Sec.	14,	T25N,	R92W
₩¥4,	NW14,	Sec.	14,	T25N,	R92W
₩ <sup>1</sup> 4,	SE¼,	Sec.	29,	T25N,	R92W
NW¼,	SE¼,	Sec.	29,	T25N,	R92W
SW¼,	ΝΕ¼,	Sec.	25,	T26N,	R92W

RECEIVED

AUG 1 5 1983

Fg Proj.Eval.Dept. Golden, CO 80403

August 1, 1983

Mr. Allen Tapp Texas Gulf Sulfer 5932 McIntyre Street Golden, Colorado 80403

Re: Sample of Abandonment Fluid

Dear Mr. Tapp:

Following is data concerning the sample of abandonment fluid you provided that was used to plug holes in Wyoming:

Mud Weight	8.7 ppg
API Filtrate	4.8 cc
Plastic Viscosity, cp	15
Yield Point, lbs/100 ft <sup>2</sup>	54
Initial Gel Strength, lbs/100 ft <sup>2</sup>	18
10 Min. Gel Strength, lbs/100 ft <sup>2</sup>	42

We now have testing equipment at our office. Please let me know when you have additional samples to be checked. Thanks for your business.

Sincerely,

Don Vesely

Scaling fluid chiractoristics for 1983 program, cot

DPV/bb

## PLATES

Map of Inventoried Land, 1983 1:4000 scale

Spinick Standard

Survey of

Participant of Participants

## Texasgulf memo

Ø - Ø

Date	September 12, 1984		
То	E.J. Poole/I.L. Turner	Location	Golden
From	C.A. Tapp	Location	Golden
Subject	1984 Lost Creek and Conoco	Program	

4 1

Attached is the final report for the 1984 Lost Creek and Conoco program. As you are aware, this program was initially presented to the Wyoming D.E.Q. in 1982. Its purpose was to rescind a Notice of Violation issued to Texasgulf by the D.E.Q. for failure to properly abandon drill holes. That Notice of Violation has been rescinded by the State and our program as presented is now complete.

stopp

. 2055-

C. A. T.

/av Attachment: Report

# Texasgulf memo

DateSeptember 5, 1984ToE.J. Poole/I.L. TurnerLocationGoldenFromC.A. TappLocationGoldenSubjectLost Creek/ Conoco - 1984 Program Summary

Texasgulf has completed its 1984 program on the Lost Creek and Conoco properties in Sweetwater County, Wyoming. In a letter to Wyoming's D.E.Q., November 24, 1982, a two year program was outlined which would inventory Texasgulf drill holes, recapping and resealing those holes which were determined to be substandard. The 1983 phase of the program inventoried seventy-five percent of the two properties. A detailed summary of that program was sent to the Wyoming D.E.Q.

The 1984 program completes the plan as presented to the D.E.Q. in 1982. Basically it involved inspecting down the hole conditions for all locateable Texasgulf drill holes to determine the adequacy of past sealing efforts. Appendix A details all holes inspected during the 1984 program. Water levels and mud column depths were measured and recorded. Concrete caps were placed on all Texasgulf holes which were not originally capped with concrete or if the original concrete cap had failed. Down the hole conditions were evaluated and any holes which did not meet our standards for sealing were resealed. Appendix B lists those drill holes which were resealed this year.

One square mile, Sec. 20, T25N R92W, containing roughly 80 drill holes was inspected in 1982 and recapped with perma-plugs. A small ledge was cut around the bore hole and the perma-plug placed on that ledge before backfilling. During the D.E.Q.'s June, 1984 inspection, several of these holes were reviewed. Mr. Alan Guile, field inspector for the D.E.Q., felt all of these were adequately capped and Texasgulf would not have to recap them with concrete caps.

E.J. Poole/I.L. Turner September 5, 1984

Approximately nine square miles of land were inventoried in 1984. A total of 427 drill holes were inspected, of which 371 holes, eighty-seven percent, were recapped with concrete caps. Fifty-six holes could not be located for one of numerous reasons. It is interesting to note that seventy-two holes, seventeen percent, were dry. Table 1 summarizes our activities on the Lost Creek and Conoco properties.

### TABLE 1

### SUMMARY OF INSPECTION ACTIVITIES

	Number of Holes Inspected	Number of Holes Recapped 1	Number of Dry Holes	Number of Holes Resealed
1982	79	79 <sup>2</sup>		·
1983	269	111	21	103
1984	427	371	72	27
Total	775	561	93	37

Upon completion of the field inventory it was determined that twentyseven holes requred resealing. All holes were resealed late in August using a mixture of water, Shur-gel, and Quick-gel. After sealing the bore hole, they were recapped with concrete caps. Abandonment fluid specifications were tested in the field and exceeded those required by the Wyoming D.E.Q.

The inspection and resealing program of 1984 completes Texasgulf's program as outlined to the Wyoming D.E.Q. in November, 1982. All issues with the State pertaining to drill hole abandonment should be resolved at this time. However, one more inspection will probably be scheduled in the spring of 1985 to review the work completed this summer.

- $\frac{1}{2}$  Some drill holes were unlocateable.
- $\frac{2}{2}$  Holes recapped with perma-plugs.
- $^3$  One hole from the 1982 program was resealed in 1983.

C. A. T.

/av Attachments - Appendix A & Appendix B APPENDIX A

Contraction of the second seco

Private (1)

Support Support

Hole ID	Original Cap	Water Depth T	<u>o</u> Mud	Recapped w/concrete
TT-1	Open Hole	Dry		Yes
TT-2	Octoplug	Dry		Yes
TT-3	Could not locate drill	hole.		
TT-4	Octoplug	Dry		Yes
TT-5	Sage Brush	174'	356 '	Yes
TT-6	Sage Brush	Dry		Yes
TT-7	Octoplug	Dry		Yes
TT-8	Sage Brush	Dry		Yes
TT-9	Could not locate drill	hole.		
TT-10	Cap was too deep to bre	ach.		Yes
TT-11	Octoplug	239'	443'	Yes
TT-12	Cap slipped down drill	hole.		Yes
TT-13	Octoplug	Dry		Yes
TT-14	Cap was too deep to bre	ach.		Yes
TT-15	Cap slipped down the ho	le.		Yes
TT-16	Octoplug	165 '	175'	Yes
TT-17	Octoplug	Dry		Yes
TT-18	Octoplug	163'	169'	Yes
TT-19	Open Hole	Dry		Yes
TT-20	Perma-plug	210'	270'	Yes
TT-21	Octoplug	Dry		Yes
TT-22	Octoplug	223'	270'	Yes
TT-23	Octoplug	226 '	261'	Yes
TT-24	Octoplug	Dry		Yes
TT-25	Octoplug	184 '	196'	Yes
TT-25(?)	Perma-plug	184'	246.1	Yes
TT-26	Octoplug	Dry		Yes
TT-27	Octoplug	Dry		Yes
TT-28	Open hole	Dry		Yes
TT-29	Octoplug	Dry		Yes
TT-30	Octoplug	187 '	202 '	Yes
TT-31	Could not locate drill			
TT-32	Octoplug	180'	233 '	Yes
TT-33	Octoplug	177 '	208'	Yes

And and a second second

Hole ID	Orinigal Cap	Dept Water	t <u>h To</u> Mud	Recapped w/concrete
TT-34	Open Hole	Dry		Yes
TT-35	Octoplug	163'	183'	Yes
TT-36	Octoplug	164 '	187 '	Yes
TT-37	Could not locate dr	ill hole.		
TT-38	Open Hole	115'	120'	Yes
TT-39	Octoplug	Dry		Yes
<b>TT-</b> 40	Octoplug	Dry		Yes
TT-41	Octoplug	151'	174'	Yes
TT-42	Could not locate dr	ill hole.		
TT-43	Could not locate dr	ill hole.		
TT-44	Octoplug	Dry		Yes
TT-45	Sage Brush	Dry		Yes
TT-46	Octoplug	177 '	189'	Yes
TT-47	Open Hole	156'	234 '	Yes
TT-48	Octoplug	Dry		Yes
TT-49	No Cap	Dry		Yes
TT-50	Octoplug	Dry		Yes
TT-51	Cap was too deep to	breach.		Yes
TT-52	Octoplug	179'	376 '	Yes
TT-53	No Cap	Dry		Yes
TT-54	Could not locate dr	ill hole.		
TT-55	Octoplug	182'	210 '	Yes
TT-56	Octoplug	Dry		Yes
TT-57	Octoplug	184'	194 '	Yes
TT-58	Could not locate dr	ill hole.		
TT-59	Cap was too deep to	breach.		Yes
TT-60	Octoplug	189'	210'	Yes
TT-61	Cap was too deep to	breach.		Yes
TT-62	Cap slipped down dr	ill hole.		Yes
TT-63	Octoplug	Dry		Yes
TT-64	Octoplug	155'	193'	Yes
TT-65	Cap was too deep to	breach.		Yes
TT-66	Could not locate dr	ill hole.		Yes
TT-67	Could not locate dr	ill hole.		Yes
TT-68	Octoplug	Dry		Yes

And the second s And the second And a second sec and the second sec Provent and Participante ( directory of the second Personal Contraction Planner, and the second And a second sec Sumary sources and

e.

Hole ID	Original Cap	Water Dept	th To	Recapped
TT-69	Could not locate dri		Mud	w/concrete
TT-70	Octoplug	198'	199'	Yes
TT-71	Octoplug	201'	204 '	Yes
TT-72	Octoplug	199'	203 '	Yes
TT-73	Octoplug	195'	234 '	Yes
TT-74	Octoplug	156'	170'	Yes
TT-75	Could not locate dril	ll hole.		
TT-76	Sage Brush	Dry		Yes
TT-77	Octoplug	167'	180'	Yes
TT-78	Sage Brush	159'	184'	Yes
TT-79	Sage Brush	Dry		Yes
TT-80	Octoplug	180'	222 '	Yes
TT-81	Octoplug	175'	232 '	Yes
TT-82	Octoplug	176'	214 '	Yes
TT-83	Open Hole	Dry		Yes
TT-84	No Cap	Dry		Yes
TT-85	Octoplug	153'	320 '	Yes
TT-86	Could not locate dri	ll hole.		
TT-87	Octoplug	161'	190'	Yes
TT-88	Could not locate dri	ll hole.		
TT-89	Octoplug	Dry		Yes
TT-90	Octoplug	Dry		Yes
TT-91	Octoplug	245 '	373'	Yes
TT-92	Octoplug	237 '	413'	Yes
TT-93	Octoplug	221 '	419 '	Yes
TT-94	Cap slipped down dri	ll hole.		Yes
TT-95	Cap was too deep to b	oreach.		Yes
TT-96	Sage Brush	Dry		Yes
TT-97	Cap slipped down dri	ll hole.		Yes
TT-98	Cap slipped down dri	ll hole.		Yes
TT-99	Perma-plug	Dry		Yes
TT-100	Perma-plug	187 '	202 '	Yes
TT-101	Could not locate dri	ll hole.		
TT-102	Perma-plug	177 '	203 '	Yes

.-

Hole		Depth To	Recapped
<u>ID</u> TT-103	<u>Orinigal Cap</u> Cap was too deep to breacl	Water <u>Mud</u>	<u>w/concrete</u> Yes
TT-104	Cap was too deep to breach		Yes
TT-104	· ·	180' 247'	Yes
TT-105	. 5	178' 200'	Yes
	1 5		
TT-107		Dry	Yes
TT-108	1 0	176' 182'	Yes
TT-109	Cap slipped down drill ho		Yes
TT-110	1 5	176' 229'	Yes
TT-111		155' 170'	Yes
TT-112	Cap was too deep to breach		Yes
TT-113	. 5	176' 214'	Yes
TT-114	, 5	186' 197'	Yes
TT-115		251' 415'	Yes
TT-116	Could not locate drill ho	le.	
TT-117	Cap slipped down drill ho	le.	Yes
TT-118	Perma-plug 2	225' >475'	Yes
TT-119	Cap was too deep to breacl	1.	Yes
TT-120	Cap was too deep to breac	1.	Yes
TT-121	Perma-plug	172' 243'	Yes
TT-122	Perma-plug I	Dry	Yes
TT-123	Perma-plug [	Dry	Yes
TT-124	Cap was too deep to breach	1.	Yes
TT-125	Perma-plug	178' 251'	Yes
TT-126	Perma-plug	179' 382'	Yes
TT-127	Perma-plug	176' 228'	Yes
TT-128	Cap was too deep to breach	1.	Yes
TT-129	Perma-plug	176' 197'	Yes
TT-130	Perma-plug I	Dry	Yes
TT-131	Perma-plug	180' 218'	Yes
TT-132	Perma-plug	184' 203'	Yes
TT-133	Perma-plug	183' 191'	Yes
TT-134	Cap slipped down drill ho	le.	Yes

3\*

Hole ID	Orinigal Cap	Water Dept	th To Mud	Recapped w/concrete
TT-135	Perma-plug	Dry		Yes
TT-136	Perma-plug	187 '	394 '	Yes
TT-137	Cap was too deep to	breach.		Yes
TT-138	Perma-plug	Dry		Yes
TT-139	Cap was too deep to	breach.		Yes
TT-140	Cap was too deep to	breach.		Yes
TT-141	Could not locate dr	ill hole.		
TT-142	Perma-plug	184'	243 '	Yes
TT-143	Perma-plug	185 '	204 '	Yes
TT-144	Perma-plug	Dry		Yes
TT-145	Open Hole	Dry		Yes
TT-146	Perma-plug	191'	207 '	Yes
TT-147	Perma-plug	195'	236 '	Yes
TT-148	Perma-plug	195'	236 '	Yes
TT-149	Perma-plug	193'	239 '	Yes
TT-150	Perma-plug	176'	249 '	Yes
TT-151	Perma-plug	179'	294 '	Yes
TT-152	Perma-plug	179'	236 '	Yes
TT-153	Perma-plug	175'	210'	Yes
TT-154	Cap slipped down dr	ill hole.		Yes
TT-155	Perma-plug	179'	272'	Yes
TT-156	Perma-plug	195 '	396 '	Yes

Hole ID	Orinigal Cap	<u>Depth T</u> Water	<u>o</u> Mud	Recapped w/concrete
TE-1	Open Hole	Dry		Yes
TE-2	Octoplug	188'	191'	Yes
TE-3	Cap was too deep to bre	ach.		Yes
TE-4	Octoplug	205 '	401'	Yes
TE-5	Sage Brush	Dry		Yes
TE-6	Octoplug	Dry		Yes
TE-7	Octopilug	Dry		Yes
TE-8	Octoplug	Dry		Yes
TE-9	Octoplug	210'	276'	Yes
TE-10	Octoplug	210'	221'	Yes
TE-11	Octoplug	Dry		Yes
TE-12	Octoplug	215'	227 '	Yes
TE-13	Could not locate drill	hole.		
TE-14	Octoplug	296 '	395 '	Yes
TE-15	Octoplug	Dry		Yes
TE-16	Could not locate drill	hole.		
TE-17	Cap was too deep to bre	ach.		Yes
TE-18	Open Hole	Dry		Yes
TE-19	Octoplug	Dry		Yes
TE-20	Octoplug	Dry		Yes
TE-21	Octoplug	207 '	238'	Yes
TE-22	Octoplug	215 '	235'	Yes
TE-23	Octoplug	210'	228'	Yes
TE-25	Octoplug	Dry		Yes
TE-26	Octoplug	221'	225'	Yes
TE-27	Could not locate drill	hole.		
TE-28	Octoplug	224 '	444 '	Yes
TE-29	Open Hole	Dry		Yes
TE-30	Octoplug	Dry		Yes
TE-31	Could not locate drill	hole.		
TE-32	Could not locate drill	hole.		
TE-33	Cap slipped down drill	hole		Yes
TE-34	Octoplug	223'	228'	Yes

c

Hole ID	Orinigal Cap	Water Depth To	Mud	Recapped w/concrete
TE-35	Octoplug	223'	235'	Yes
TE-36	Octoplug	Dry		Yes
TE-37	Octoplug	219'	277 '	Yes
TE-39	No Cap	216'	220'	Yes
TE-40	Could not locate drill	hole.		
TE-41	Could not locate drill	hole.		
TE-42	Perma-plug	219'	228'	Yes
TE-43	Perma-plug	218'	226 '	Yes
TE-44	Cap slipped down drill	hole.		
TE-45	Octoplug	211'	221'	Yes
TE-46	No Cap	Dry		Yes
TE-47	Octoplug	204 '	248'	Yes
TE-48	No Cap	212'	225 '	Yes
TE-49	Could not locate drill	hole.		
TE-50	Octoplug	209 '	234 '	Yes
TE-51	Octoplug	Obstruction in h	ole @ about 100	'Yes
TE-52	Octoplug	209'	247 '	Yes
TE-53	Octoplug	210'	238'	Yes
TE-54	Could not locate drill	hole.		
TE-55	Could not locatd drill	hole.		
TE-56	Open Hole	203 '	230'	Yes
TE-57	Octoplug	210'	235 '	Yes
TE-58	Could not locate drill	hole.		
TE-59	Could not locate drill	hole.		
TE-60	Could not locate drill	hole.		
TE-61	Octoplug	209 '	225 '	Yes
TE-62	Could not locate drill	hole.		
TE-63	Octoplug	Dry		Yes
TE-64	Open Hole	195'	224 '	Yes
TE-65	Octoplug	Dry		Yes
TE-66	Octoplug	Dry		Yes
TE-67	Octoplug	191'	389 '	Yes
TE-68	Could not locate drill	hole.		
TE-69	Octoplug	191'	209 '	Yes

Hole		Dept	th To	Recapped		
ID	Orinigal Cap	Water	Mud	w/concrete		
TE-70	Octoplug	189'	252 '	Yes		
TE-71	Octoplug	Dry		Yes		
TE-72	Octoplug	192'	211'	Yes		
TE-73	Octoplug	Dry		Yes		
TE-74	Octoplug	227 '	249 '	Yes		
TE-75	Octoplug	229 '	270'	Yes		
TE-76	Octoplug	211'	248'	Yes		
TE-77	Open Hole	Dry		Yes		
TE-78	Octoplug	Dry		Yes		
TE-79	Open Hole	214 '	308 '	Yes		
TE-80	Octoplug	Dry		Yes		
TE-81	Octoplug	?	250'	Yes		
TE-82	Octoplug	212 '	253 '	Yes		
TE-83	Octoplug	207 '	326 '	Yes		
TE-84	Octoplug	212'	241'	Yes		
TE-85	Could not locate dr	ill hole.				
TE-86	Open Hole	223'	275 '	Yes		
TE-87	Octoplug	233 '	238 '	Yes		
TE-88	Octoplug	216 '	219'	Yes		
TE-89	Octoplug	194 '	230'	Yes		
TE-90	Perma-plug	209 '	243 '	Yes		
TE-91	Cap was too deep to	breach.		Yes		
TE-92	Perma-plug	204 '	252 '	Yes		
TE-93	Perma-plug	205 '	225 '	Yes		
TE-94	Perma-plug	205 '	227 '	Yes		
TE-95	Could not locate dr	ill hole.				
TE-96	Perma-plug	203 '	207 '	Yes		
TE-97	Cap slipped down dr	ill hole.				
TE-101	Perma-plug	195'	199 '	Yes		

Hole ID	Orinigal Cap	Water Dep	<u>th To</u> Mud	Page 9 of 14 Recapped w/concrete
TGC-1-15	Could not locate dril	l hole.		
TGC-2-15	Could not locate dril	l] hole.		
TG-3-15	Could not locate dril	l hole.		
TG-4-15	Perma-plug	104'	200 '	Yes
TG-5-15	Perma-plug	90'	233'	Yes
TG-6-15	Perma-plug	94 '	229 '	Yes
TG-7-15	Perma-plug	99 '	115 '	Yes
TG-8-15	Open Hole	113'	200 '	Yes
TG-9-15	Perma-plug	92 '	245 '	Yes
TG-10-15	Perma-plug	97'	225 '	Yes
TG-11-15	Perma-plug	100'	231'	Yes
TG-1-17	Perma-plug	160'	2201	Vee
TG-3-17	Perma-plug	155 '	238' 160'	Yes
TG-5-17	Perma-plug	155		Yes
TG-6-17	Perma-plug	166 '	368 ' 395 '	Yes Yes
TG-7-17	Perma-plug	157'	239 '	Yes
TG-8-17	Cap slipped down dril		239	Tes
TG-9-17	Perma-plug	151'	163'	Vec
TG-10-17		151		Yes
TG-11-17	Perma-plug		313'	Yes
	Perma-plug	159' 1521	186'	Yes
TG-12-17	Perma-plug	152'	154 '	Yes
TG-13-17 TG-15-17	Perma-plug	158'	288'	Yes
	Perma-plug	1671	341'	Yes
TG-16-17	Perma-plug	167'	241 '	Yes
TG-17-17	Perma-plugg	160'	205 '	Yes
TG-18-71	Perma-plug	167'	190'	Yes
TG-19-17	Perma-plug	156'	203 '	Yes
TG-20-17	Perma-plug	161'	294 '	Yes
TG-21-17	Perma-plug	163'	357 '	Yes
TG-22-17	Perma-plug	171'	248 '	Yes
TG-23-17	Perma-plug	155'	186 '	Yes
TG-24-17	Perma-plug	157'	201'	Yes

e (

phonoid,

Surger Street

And a second sec

.

Contraction of the

2

Hole ID	Orinigal Cap	Water Dep	th To <u>Mud</u>	Recapped w/concrete
TG-25-17	Perma-plug	159'	221'	Yes
TG-26-17	Perma-plug	158'	166'	Yes
TG-27-17	Perma-plug	163'	271'	Yes
TG-28-17	Perma-plug	162'	225 '	Yes
TG-29-17	Perma-plug	161'	238 '	Yes
TG-30-17	Perma-plug	168'	243 '	Yes
TG-32-17	Perma-plug	160'	196'	Yes
TG-33-17	Perma-plug	161'	200 '	Yes
TG-34-17	Perma-plug	158'	275 '	Yes
TG-35-17	Perma-plug	152'	333 '	Yes
TG-36-17	Cap was too deep to	breach.		Yes
TG-37-17	Perma-plug	161'	317 '	Yes
TG-38-17	Perma-plug	151'	176'	Yes
TG-39-17	Cap was too deep to	breach.		Yes
TG-40-17	Cap was too deep to	breach.		Yes
TG-41-17	Cap was too deep to	breach.		Yes
TG-42-17	Cap was too deep to	breach.		Yes
TG-43-17	Perma-plug	161'	438 '	Yes
TG-44-17	Perma-plug	166'	286 '	Yes
TG-45-17	Cap was too deep to	breach.		Yes
TG-46-17	Cap slipped down dri	ill hole.		Yes
TG-47-17	Cap was too deep to	breach.		Yes
TG-48-17	Cap was too deep to	breach.		Yes
TG-49-17	Perma-plug	151'	159 '	Yes
TG-50-17	Cap was too deep to	breach.		Yes
TG-51-17	Concrete cap. Did no	ot remove.		
TG-52-17	Concrete cap. Did no	ot remove.		
<b>TG-1-1</b> 8	Perma-plug	151'	156'	Yes
TG-2-18	Perma-plug	156'	242 '	Yes
TG-3-18	Cap was too deep to	breach.		Yes
TG-4-18	Perma-plug	164 '	176 '	Yes
TG-5-84	Perma-plug	159'	168'	Yes
TG-6-18	Perma-plug	166'	306 '	Yes

ŕ.,

				-
Hole		Dept	th To	Recapped
ID	<u>Orinigal Cap</u>	Water	Mud	w/concrete
TC 7 10		1071	0041	.,
TG-7-18	Perma-plug	167'	224 '	Yes
TG-8-18	Perma-plug	157'	341'	Yes
TG-9-18	Could not locate drill			
TG-10-18	Perma-plug	166'	298'	Yes
TG-11-18	Could not locate drill			
TG-12-18	Perma-plug	173'	206 '	Yes
TG-13-18	Perma-plug	154'	379'	Yes
TG-14-18	Could not locate drill			
TG-15-18	Perma-plug	156'	238'	Yes
T <b>G-1</b> 6-18	Cap slipped down dill h			
TGC-17-18	Cap was too deep to bre	each.		Yes
TGC-18-18	Perma-plug	155'	369 '	Yes
TGC-19-18	Perma-plug	155'	389 '	Yes
TG-20-18	Cap was too deep to bre	each.		Yes
TGC-20-18	Cap was too deep to bre	each.		Yes
TG-21-18	Cap was too deep to bre	each.		Yes
TGC-21-18	Cap slipped down drill	hole.		Yes
TG-22-18	Cap was too deep to bre	each.		Yes
TG-23-18	No Cap.	Dry		Yes
TG-24-18	Cap was too deep to bre	each.		Yes
TG-25-18	Cap was too deep to bre	each.	-	Yes
TG-27-18	No Cap.	Dry		Yes
TG-1-19	Perma-plug	145'	223 '	Yes
TGC-1-19	Perma-plug	154 '	180'	Yes
TGC-1A-60-19	Angle hole. Could not p	probe.		Yes
TGC-1A-45-19	Angle hole. Could not p			Yes
TG-2-19	Perma-plug	143'	144 '	Yes
TGC-2-19	Could not breach cap.			Yes
TG-3-19	Perma-plug	129'	139'	Yes
TG-4-19	Perma-plug	138'	<b>&gt;</b> 450 '	Yes
TG-5-19	Perma-plug(open)	145'	215 '	Yes
TG-6-19	Cap was too deep to bre		~ <del>-</del> - V	Yes
TG-7-19	Cap slipped down drill			Yes
		nore.		162

۰ .

Hole ID	Orinigal Cap	Water Dep	th To <u>Mud</u>	Recapped w/concrete
TG-8-19	Cap failed at surface.	. Could not p	robe.	Yes
TG-9-19	Perma-plug(open)	158'	<b>7</b> 450'	Yes
TG-10-19	Perma-plug	154'	283'	Yes
TG-11-19	Perma-plug	Dry		Yes
TG-12-19	Perma-plug	160'	331 '	Yes
TG-13-19	Cap slipped down dril	l hole.		Yes
TG-14-19	Perma-plug	159'	175 '	Yes
TG-15-19	Cap was too deep to br	reach.		Yes
TG-16-19	Could not locate dril	l hole.		
TG-17-19	Cap was too deep to br	reach.		Yes
TG-18-19	Cap failed at surface.	. Could not p	robe.	Yes
TG-19-19	Cap was too deep to br	reach.		Yes
TG-20-19	Cap was too deep to br	reach.		Yes
TG-21-19	Cap slipped down dril	l hole.		Yes
TG-22-19	Cap was too deep to br	reach.		Yes
TG-23-19	Cap was too deep to br	reach.		Yes
TG-24-19	Cap was too deep to br	reach.		Yes
TG-25-19	Cap was too deep to br	reach.		Yes
TG-1A-75-19	Angle hole. Could not	probe.		Yes
TG-1A-60-19	Angle hole. Could not	probe.		Yes
TG-1-21	Perma-plug	144'	316 '	Yes
TG-2-21	Perma-plug	142'	366 '	Yes
TG-3-21	Cap was too deep to bi	reach.		Yes
TG-4-21	Perma-plug	118'	414 '	Yes
TG-5-21	Cap was too deep to bi	reach.		Yes
TG-6-21	Perma-plug	129'	142 '	Yes
TG-7-21	Perma-plug	132'	296 '	Yes
TG-8-21	Cap slipped down dril	l hole.		Yes
TG-9-21	Perma-plug	116'	159 '	Yes
TG-10-21	Cap was too deep to bi	reach.		Yes
TG-11-21	Perma-plug	124 '	282 '	Yes
TG-12-21	Perma-plug	131'	279'	Yes
TG-13-21	Perma-plug	121'	421'	Yes
TG-14-21	Perma-plug	128'	259'	Yes

And a second sec

Contraction of the second

and the second s

And a second sec

and the second s

(

Hole ID	Orinigal Cap	Water Depti	<u>To</u> Mud	Recapped w/concrete
TG-14-21	Could not locate drill	hole.		
TG-15-21	Perma-plug	128'	429 '	Yes
TG-17-21	Perma-plug	129'	145'	Yes
TG-18-21	Perma-plug	121'	166'	Yes
TG-19-21	Perma-plug	133'	291'	Yes
TG-20-21	Cap slipped down drill	hole.		Yes
TG-21-21	Perma-plug	109'	319'	Yes
TG-22-21	Perma-plug	115'	116 '	Yes
TG-23-21	Cap slipped down drill	hole.		Yes
TG-24-21	Cap was too deep to bre	ach.		Yes
TG-25-21	Perma-plug	100'	312'	Yes
TG-26-21	Open	Dry		Yes
TG-28-21	Perma-plug	127'	131'	Yes
TG-29-21	Perma-plug	115'	308 '	Yes
TG-30-21	Cap slipped down drill	hole.		Yes
TG-31-21	Sage Brush	110'	113'	Yes
No ID	Drill site, but could n	ot locate dri	ll hole.	
TG-32-21	Perma-Plug	Dry		Yes
TG-33-21	Sage Brush	Dry		Yes
TG-34-21	Perma-plug	88'	117'	Yes
TG-35-21	Perma-plug	80'	115 '	Yes
TG-36-21	Could not locate drill	hole.		
TG-37-21	Cap was too deep to bre	ach.		Yes
TG-38-21	Cap slipped down drill	hole.		Yes
TG-39-21	Perma-plug	88'	202 '	Yes
TG-40-21	Perma-plug	86 '	93'	Yes
TG-41-21	Cap was too deep to bre	each.		Yes
TG-42-21	Perma-plug	112'	345	Yes
TG-44-21	Concrete cap. Did not r	emove.		
TG-45-21	Concrete cap. Did not r	emove.		
TG-46-21	Could not locate drill	hole.		
TG-47-21	Concrete cap. Did not r	emove.		
TG-48-21	Cap was too deep to bre	each.		Yes
TG-49-21	Could not locate drill	hole.		

Page 14 of 14

Hole ID	Orinigal Cap	Water Depth T	o Mud	Recapped w/concrete
TG-50-21 TG-51-21	Concrete cap. Did not re Concrete cap. Did not re			
TG-3-21(?)	Sage Brush	981	218'	Yes
TGC-27-21	Could not locate drill H	nole.		
TGC-16-21	Could not locate drill H	nole.		
TG-1-22	Could not locate drill A			
		97'	279'	Yes
TG-2-22	Perma-plug	-		165
TG-3-22	Perma-plug	98'	284 '	Yes

TOTAL NUMBER OF HOLES INSPECTED:	427	100%
TOTAL NUMBER OF HOLES CAPPED:	371	87%
NUMBER OF DRY HOLES:	72	17%
NUMBER OF WET HOLES:	213	50%
NUMBER OF UNPROBED HOLES:	142	33%

/av

## APPENDIX B

difference of

Constant Contraction

and the second

Contraction of the second

Street,

Second Contraction

Control investments

and the second second

### RESEALED DRILL HOLES

Hole Number Location TT-5 SW1/4, NW1/4, Sec. 19, T25N, R92W TT-11 SW1/4, SE1/4, Sec. 7, T25N, R92W TT-52 SE1/4, NE1/4, Sec. 24, T25N, R93W TT-91 SW1/4, SE1/4, Sec. 7, T25N, R92W TT-92 SE1/4, SW1/4, Sec. 7, T25N, R92W TT-93 NW1/4, NE1/4, Sec. 18, T25N, R92W TT-115 NW1/4, NE1/4, Sec. 13, T25N, R93W TT-118 NE1/4, NW1/4, Sec. 18, T25N, R92W TT-126 SW1/4, NW1/4, Sec. 19, T25N, R92W TT-136 SW1/4, NE1/4, Sec. 24, T25N, R93W TT-156 SW1/4, NE1/4, Sec. 24, T25N, R93W TE-4 NW1/4, NE1/4, Sec. 24, T25N, R93W TE-14 NW1/4, NW1/4, Sec. 23, T25N, R93W TE-28 NE1/4, NW1/4, Sec. 24, T25N, R93W TE-67 SW1/4, NE1/4, Sec. 24, T25N, R93W TG-5-17 SW1/4, SW1/4, Sec. 17, T25N, R92W SW1/4, SW1/4, Sec. 17, T25N, R92W TG-6-17 TG-21-17 SE1/4, SW1/4, Sec. 17, T25N, R92W TG-43-17 SW1/4, SW1/4, Sec. 17, T25N, R92W SE1/4, SE1/4, Sec. 18, T25N, R92W TG-13-18 TGC-18-18 SE1/4, SE1/4, Sec. 18, T25N, R92W SE1/4, NE1/4, Sec. 19, T25N, R92W TG-4-19 NE1/4, NE1/4, Sec. 19, T25N, R92W TG-9-19 TG-2-21 NW1/4, NW1/4, Sec. 21, T25N, R92W TG-4-21 NE1/4, NW1/4, Sec. 21, T25N, R92W TG-13-21 NE1/4, NW1/4, Sec. 21, T25N, R92W TG-15-21 NW1/4, NE1/4, Sec. 21, T25N, R92W

January 15, 2007

Melissa L. Bautz Senior Environmental Analyst State of Wyoming Department of Environmental Quality Land Quality Division 510 Meadowview Drive Lander, WY 82520

RE: Drilling Notification No. 334DN Amendment, NFU Wyoming, LLC

Dear Ms. Bautz,

NFU Wyoming, LLC, an affiliate of Ur-Energy USA, has completed the installation of 17 new monitoring wells within the Lost Creek Project area, T25N, R92 and 93W, Sweetwater County, Wyoming. These water wells were also permitted through the State Engineer's Office.

During the 2006 field activities, a total of 19 historic exploration holes near our new wells were found to be open. This includes seven holes drilled in 2005 by NFU Wyoming in which the plug gel did not sufficiently stabilize. These holes were reamed out, plugged with grout, and capped with 25 feet of cement to assure the quality and integrity of our hydrological testing results. This plugging method was approved by the WDEQ for use by NFU Wyoming in 2006. This part of the project constituted over 11,600 feet of reaming and plugging at an additional cost to NFU Wyoming of \$30,000.

For reclamation, each well and historic drilling site was then recontoured, the stockpiled topsoil was replaced, and the site was reseeded. A detailed, site-specific vegetation survey conducted by Keammerer Ecological Consultants, Inc. in 2006 indicated that the vegetation types growing on the site are slightly different than the standard BLM recommended seed mix. The new mix and the seeding proportions are indicated on the completion reports. With the permission of both the WDEQ and the BLM, this new seed mix was used at each disturbed site in order to promote re-vegetation similar to the existing conditions.

Per the Reporting Requirements, Section 8, Form 9DN, "Department of Environmental Quality, Land Notification of Intent to Explore for Noncoal Minerals by Drilling", we are attaching the following lists of information in duplicate to your office and the State Engineer's office with a copy to the U.S. BLM office in Rawlins.

- 1. A tabulation of the monitoring wells and historic plugged holes, including quadrangle location, northing and easting coordinates, elevation, total depth/depth plugged, date completed/plugged, land ownership, disturbance, reclamation, seed mix, seeding method, and seeding date.
- 2. A tabulation of the wells by ¼, ¼ Section, Township, and Range
- 3. A map on USGS quadrangle format showing the location of the wells and an outline of the general area of the exploration activities.

If you need any additional information, please do not hesitate to contact either myself of Dawn Schippe at 720-981-4588.

Sincerely,

Harold A. Backer VP US Operations

Cc: State Engineer's Office Mark Newman, U.S. BLM

### 2006 Drilling Program WDEQ Completion Report NFU Wyoming, LLC - Lost Creek Project - Sweetwater County Drilling Notification Number #334DN

Operator: NFU Wyoming, LLC Operator Address: 10758 W. Centennial Road, Suite 200, Littleton, CO 80127 Drilling Notification Number: 334DN

			WY State Pla	ne, NAD 27									1	
	WY State Engineer	USGS 7.5 Minute	West Cent	tral Zone	Pilot Hole							Seed Mix (Approved by WDEQ		
Hole ID	Permit Number	Quad	N	E	TD	Date Completed	Capping Method	Plugging Method	Ownership	Disturbance	Reclamation	and BLM)	Seed Method	Seeding
LC15M	U.W. 175260	Osbourne Well	534,823	744,546	350	9/13/2006	Monitoring Well was	Monitoring Well is	US Department of the	15' x 25'	Stockpiled topsoil and replaced	Total 19.5 lb/acre: Thickspike	Seed spread	12/22/2006
							installed and is	operational.	Interior US BLM	Disturbance, all	after completion of drilling and	wheatgrass 4 lb/acre; Western	with Kubota	
							operational. 4 1/2"	Schedule 40 PVC		drilled from	recontouring of site	wheatgrass 2 lb/acre; Indian	tractors and	
							diameter PVC well,	pipe anchored in		same pad		ricegrass 2 lb/acre; Prairie	Truax no-till	
							protruding	ground by cement				sandreed 2 lb/acre; Great Basin	seed drills;	
							approximately 2' out	(except LC29, 30,				wildrye 2 lb/acre; Big sagebrush	fertilizer will be	
							of ground with 1/2,	and 31M which are				1 lb/acre; Rubber rabbitbrush 1	spread in Spring	
							3/4, or 1 hp pump	gravel packed to 20'				lb/acre; Winterfat (Ceratoides	2007	
							installed. Entire	below surface, above				lanata) 1.5 lb/acre; Slender		
							assembly protected	is 15' bentonite chips,				wheatgrass (Agropyron		
							by locking well cover	with 5' soil on top), 7				trachycaulum) 2.5 lb/acre;		
							anchored below	7/8" diameter drilled				Sandberg Bluegrass (Poa		
							ground surface.	hole.				secunda) 1.5 lb/acre		
LC16M	U.W. 175260	Osbourne Well	534,820	744,562	472	9/13/2006	Same as Above	Same as Above	Same as Above		Same as Above	Same as Above	Same as Above	
LC17M	U.W. 175260	Osbourne Well	534,840	744,562	575	9/13/2006	Same as Above	Same as Above	Same as Above		Same as Above	Same as Above	Same as Above	
LC29M	U.W. 175260	Osbourne Well	534,837	744,547	171	9/21/2006	Same as Above	Same as Above	Same as Above		Same as Above	Same as Above	Same as Above	12/22/2006
LC18M	U.W. 175261	Osbourne Well	535,318	743,362	350	9/21/2006	Same as Above	Same as Above	Same as Above	15' x 25'	Same as Above	Same as Above	Same as Above	
LC19M	U.W. 175261	Osbourne Well	535,317	743,378	463	9/21/2006	Same as Above	Same as Above	Same as Above	Disturbance, all	Same as Above	Same as Above	Same as Above	
LC20M	U.W. 175261	Osbourne Well	535,332	743,377	543	9/22/2006	Same as Above	Same as Above	Same as Above	drilled from	Same as Above	Same as Above	Same as Above	12/21/2006
		<u></u>		700 077	440	0/04/0000	Oren an Alberra	O	Come of Alberta	15' x 25'	Company Alberta	Come of About	0	10/01/0000
LC21M	U.W. 175262	Antelope Reservoir	532,850	736,277	410	9/21/2006	Same as Above	Same as Above	Same as Above		Same as Above	Same as Above	Same as Above	
LC22M		Antelope Reservoir	532,850	736,292	592	9/22/2006	Same as Above		Same as Above	4 . ,	Same as Above	Same as Above	Same as Above	
LC23M		Antelope Reservoir	532,835	736,292	634	9/22/2006	Same as Above		Same as Above	4	Same as Above	Same as Above	Same as Above	
LC30M	U.W. 175262	Antelope Reservoir	532,836	736,276	236	9/21/2006	Same as Above	Same as Above	Same as Above	same pad	Same as Above	Same as Above	Same as Above	12/21/2006
100414	U.W. 175263	Osbourne Well	535,203	744,580	542	9/22/2006	Same as Above	Same as Above	Same as Above	15' x 25'	Same as Above	Same as Above	Same as Above	12/22/2006
LC24M	0.00.175263	Osbourne vven	535,203	744,360	042	9/22/2000	Same as ADOVE	Same as Above	Same as ADOVE	10 X 20		Same as Above	Same as ADOVE	12/22/2000
LC25M	U.W. 175264	Osbourne Well	534.621	743,406	380	9/22/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/21/2006
LOZUNI	0.00.175204		554,021	740,400	300	312212000	Came as Above	Came as Above	Came as Above	Came as Above		Came as Above	Came as Above	1212112000
LC26M	U.W. 175265	Osbourne Well	534,832	748,203	436	9/22/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/22/2006
U	0.00.110200		00,002			0,11,1000								
LC27M	U.W. 175266	Osbourne Well	539.018	753,260	477	9/27/2006	Same as Above	Same as Above	State	Same as Above	Same as Above	Same as Above	Same as Above	12/22/2006
	0,			/	,									
LC28M	U.W. 175267	Battle Springs	524,437	733,364	563	9/22/2006	Same as Above	Same as Above	US DOI BLM	Same as Above	Same as Above	Same as Above	Same as Above	12/21/2006
LC31M	U.W. 175268	Battle Springs	524,434	733,380	191	9/22/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/22/2006

Maintaining all completed water wells under State Engineer Permits listed above

#### Plugged Holes

### 2006 Drilling Program WDEQ Completion Report NFU Wyoming, LLC - Lost Creek Project - Sweetwater County Drilling Notification Number #334DN

### Historic Hole Plugging and Reclamation

Operator: NFU Wyoming, LLC Operator Address: 10758 W. Centennial Road, Suite 200, Littleton, CO 80127 Drilling Notification Number: 334DN

\*\*NOTE\*\* The LC holes listed were drilled in 2005 by NFU Wyoming, LLC, and plugged with plug gel as per WDEQ regulations. Upon re-opening the 7 holes listed below, the gel was found to not sufficiently plug the holes for conducting pump tests on aquifers. For holes in the vicinity of NFU Wyoming's 2006 wells, the plug gel was replaced with grout, a denser plugging material, to the depth listed with a 25' cement cap.

\*\*NOTE\*\* The TE and TT holes listed below were drilled in the 1970s. Since they are in the vicinity of NFU Wyoming's western pump test, they were opened, cleaned out, and replugged with grout to the depth indicated and capped with 25' of cement.

The cost of locating, reaming out, plugging, and reclaiming the 19 holes came to approximately \$30,000, with a total of 11,620 ft of reaming and plugging.

		WY State Pla												
	USGS 7.5 Minute	West Cen	tral Zone		Depth	Date		Diversion a Mathead	a	Disturbance	Declamation	· · · · · · · · · · · · · · · · · · ·	Danal Mathead	Deadline
Hole ID	Quad	N	E	TAINED TO CONTRACTOR OF THE OWNER	Plugged	Plugged	CONTRACTOR OF A DESCRIPTION OF A DESCRIP	the second s		Disturbance	Reclamation	Seed Mix (Approved by WDEQ and BLM)		Seeding
LC10A	Osbourne Well	535,299	743,395	6950	250	9/8/2006		Original plug gel		15' x 25'	Stockpiled	Total 19.5 lb/acre: Thickspike wheatgrass	Seed spread	12/21/2006
							1	from 2005 was	of the Interior	Disturbance	topsoil and	4 lb/acre; Western wheatgrass 2 lb/acre;	with Kubota	
							added after plug	insufficient,	US BLM		replaced after	Indian ricegrass 2 lb/acre; Prairie sandreed	tractors and	
								plugged in 2006			completion of	2 lb/acre; Great Basin wildrye 2 lb/acre; Big		
							, ,	with grout from 25'			drilling and	sagebrush 1 lb/acre; Rubber rabbitbrush 1	seed drills;	
							onto steel ring,	below surface to			recontouring of	Ib/acre; Winterfat (Ceratoides lanata) 1.5	fertilizer will be	
							attached to	TD or depth			site	Ib/acre; Slender wheatgrass (Agropyron	spread in Spring	
			-				cement by	indicated.	ł			trachycaulum) 2.5 lb/acre; Sandberg	2007	
							aluminum wire.					Bluegrass (Poa secunda) 1.5 lb/acre		
	-							0 11						10101/0000
LC10C	Osbourne Well	535,304	743,399	6950	600		Same as Above	Same as Above	Same as Above			Same as Above	Same as Above	12/21/2006
LC12C	Osbourne Well	534,813	744,601	6935	800		Same as Above	Same as Above	Same as Above		Same as Above		Same as Above	12/22/2006
LC4C	Osbourne Well	534,908	743,606	6940	600			Same as Above	Same as Above		Same as Above		Same as Above	12/21/2006
LC5C	Osbourne Well	534,824	743,397	6942	600			Same as Above	Same as Above		Same as Above			
LC7C	Osbourne Well	534,756	741,947	6932	600			Same as Above	Same as Above		Same as Above		Same as Above	
LC8C	Osbourne Well	535,399	743,396	6943	600			Same as Above	Same as Above		Same as Above		Same as Above	
TE69	Antelope Reservoir	532,781	736,195	6922	650	9/12/2006	Same as Above	Grouted from 25'	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/21/2006
								below surface to						
								TD or depth						
							-	indicated.						
TE71	Antelope Reservoir	532,691	736,211	6923	650			Same as Above	Same as Above		Same as Above			
TE72	Antelope Reservoir	532,791	736,105	6924	650			Same as Above	Same as Above		Same as Above		Same as Above	
TE73	Antelope Reservoir	532,902	736,216	6926	650			Same as Above	Same as Above		Same as Above		Same as Above	12/21/2006
TE89	Antelope Reservoir	532,895	736,202	6926	650			Same as Above	Same as Above		Same as Above			
TT27	Antelope Reservoir	532,993	736,379	6929	650			Same as Above	Same as Above		Same as Above		Same as Above	
TT61	Antelope Reservoir	535,014	744,603	6939	650			Same as Above	Same as Above		Same as Above			
TT146	Antelope Reservoir	532,967	736,309	6929	650			Same as Above	Same as Above	1	Same as Above			12/21/2006
TT147	Antelope Reservoir	532,918	736,308	6927	580			Same as Above	Same as Above		Same as Above		Same as Above	
TT148	Antelope Reservoir	532,918	736,298	6927	580			Same as Above	Same as Above		Same as Above		Same as Above	12/21/2006
TT149	Antelope Reservoir	532,866	736,306	6925			and a second sec	Same as Above	Same as Above		Same as Above		Same as Above	12/21/2006
TT156	Antelope Reservoir	532,918	736,287	6927	560	9/15/2006	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	Same as Above	12/21/2006