



Figure 1 - View of the 1117ET gravel processing area on October 24, 2007.



Figure 2 - View of the same area during the current inspection on July 15, 2010



Figure 3 - View S of Pond No. 1 (see attached map). A topsoil stockpile is evident to the left of the pond (arrow).



Figure 4 - View of uncovered liner



Figure 5 - View S of Pond No. 2. Topsoil is stockpiled adjacent to the pond on the left.



Figure 6 – View N of Pond No. 3. Topsoil is stockpiled on the right in this view.

Snake River Sporting Club, LMO 1117
NW¼SE¼ Sec.32, T.39N., R.116W., Teton County, Wyoming
Unreclaimed Mining Disturbances as of 2009



Base Map = 2009 National Agriculture Imagery Program (NAIP) Aerial Photography.
Map prepared 10/11/10 by J. Erickson, Lander DEQ/LQD

C:\Documents and Settings\jeric\My Documents\Jeric\Data\ET\Canyon Club 1117\ET\2009 NAIP Imagery Map.mxd