FILED
APR 18 2011

NON-COAL MINING AND EXPLORATION

INSPECTION FORM

INSPECTION FORM

Jim Ruby, Executive Secretary
Land Quality Division / 510 Meadowview Dr. / Lander, WY 82520

Environmental Quality Land (307) 332-3047 FAX: (307) 332-7726



Permit/License No.: 578ET			Inspection Date: 9/10/07
Mineral : Sand & Gravel			REC
Operator: Carbon Energy			Date Permit Issued: 5/23/85 Acres: 2.4
Licensee: NA			Last Annual Report Received: 4/01/99
Pit Name: Scoria Pit			Date of Last Inspection: 7/18/97
Inspector Name: Steve Platt			Current Bond Amount: \$1,000 [\$300/acre]
Participants: <u>NA</u>			Landowner: Private State Federal
Status: Active In Reclama	tion [☐ Inactive ☐ Abandoned	Mineral Owner: ☐ Private ☒ State ☐ Federal
A	dequate	2	Comments
Permit Signs	No		
Topsoil Signs	No		
Topsoil Salvage	√ -√	Three topsoil st	tockpiles present.
Topsoil Protection			
Native Disturbance	No		
Erosion	√		nighly erosive; some sheet erosion on-site & in areas (Photo 2).
Roads & Culverts	√	Access road ha	s eroded & channel below road culvert (Photos 1, 3 &
Impoundments	No		
Highwalls	√	Approximately	12 feet tall in excavated trench (Photos 5 & 6).
Blasting	N/A		
Solid Waste on site	N/A		
Fuel Storage / Spills	N/A		
List equipment on site	N/A		
Dust concerns	No		
Reclamation	No		
Vegetation established	N/A		
Weeds present	V		
Slope / Grading	No		

Through Drainage √					
GPS INFORMATION:					
Total Disturbed Acreage: 1 acre + road	Rover Filename: <u>NA</u>				
Permitted Acreage: 2.4	GPS Model: <u>NA</u>				
Access Road Acreage: >1 acre	Photos attached: \boxtimes Y or \square N				
Other features: NA	Map attached: \square Y or \boxtimes N				
*ACTIONS REQUIRED BY OPERATOR: The site should be reclaimed immediately. ADDITIONAL COMMENTS: Corporate filing with the Secretary of State of WY was expired as of 03/04.					
Inspector Signature / Date: Series Class 9/19/07 Attachments: Photos GPS Map Other					
xc: Cheyenne DEQ/LQD WDEQ/LQD District 2 Supervisor - Lander Carbon Energy, 2325 W Main, Riverton, WY State Lands - Cheyenne					







LQD

APR 0 8 11

RECEIVED

Photo 1. View looking east across the upper portion of the access road toward the scoria outcrop & scoria trench. eFrame IMG_0553.



Photo 2. View of minor native drainage up stream of the access road and culvert where background sheet erosion was extensive. eFrame IMG_0565 .

INSPECTION REPORT

MINE

: Carbon Energy, Scoria Pit, Limited Mining Operation #578ET

DATE OF INSPECTION: September 10, 2007

PREPARED BY

: Steve Platt, Environmental Senior Analyst, WDEQ-LQD District 2

APR 0 8 11
RECEIVED




Photo 3. View of upstream end of the culvert under the access road where erosion was minor. eFrame IMG_0559.



Photo 4. View of downstream end of the culvert under the access road where erosion was ongoing. eFrame IMG_0560.

INSPECTION REPORT

MINE : Carbon Energy, Scoria Pit, Limited Mining Operation #578ET

DATE OF INSPECTION: September 10, 2007

PREPARED BY : Steve Platt, Environmental Senior Analyst, WDEQ-LQD District 2




Photo 5. View looking west along the excavated trench where highwalls were present. eFrame IMG_0562.




Photo 6. View looking east along the scoria trench where highwalls were present. eFrame IMG_0564.

INSPECTION REPORT

MINE : Carbon Energy, Scoria Pit, Limited Mining Operation #578ET

DATE OF INSPECTION: September 10, 2007

PREPARED BY : Steve Platt, Environmental Senior Analyst, WDEQ-LQD District 2