

Table MU1 4-2b QA/QC Monitor Well Sampling Events

Sampling	Duplicate	Field Blank	Comments
4/20/2009	M-129	M-130	Duplicate from well M-110
4/21/2009	M-131	M-132	Duplicate from well MP-110
4/22/2009	M-133	M-134	Duplicate from well MU-107
4/23/2009	M-135	M-136	Duplicate from well MP-105
5/4/2009	M-129	M-130	Duplicate from well M-110
5/5/2009	M-131	M-132	Duplicate from well MO-110
5/6/2009	M-133	M-134	Duplicate from well MU-107
5/7/2009	M-135	M-136	Duplicate from well MU-105
5/18/2009	M-129	M-130	Duplicate from well M-110
5/19/2009	M-131	M-132	Duplicate from well MO-110
5/20/2009	M-133	M-134	Duplicate from well MU-107
5/21/2009	M-135	M-136	Duplicate from well MU-105
6/1/2009	M-129	M-130	Duplicate from well M-110
6/2/2009	M-131	M-132	Duplicate from well MO-110
6/3/2009	M-133	M-134	Duplicate from well MU-107
6/4/2009	M-135	M-136	Duplicate from well MU-105
11/18/2009 ¹	--	--	
12/1/2009 ¹ 12/15/2009	--	MO-115	
12/15/2009 ¹	MO-120A	--	Duplicate from well M-120A
12/16/2009 ¹	--	--	
1/5/2010 ¹	--	--	
1/14/2010 ¹	MO-120	--	Duplicate from well MO-114
2/2/2010 ¹	--	B-2	
2/3/2010 ¹	--	--	

¹ Few samples collected during the sampling event; therefore, one blank sample and one duplicate sample were collected at least every 20 samples in accordance with the Groundwater Monitoring Program (Attachment OP-8 of the Main Permit Application).