

Figure D1-E&W-2b - Photographs of Existing West Access Road - July 29, 2009

a) Intersection with Wamsutter/Crooks Gap Road, facing north.



b) Puddle formed by rain approximately 2.5 miles east of the Wamsutter/Crooks Gap Road, facing east.



c) Typical road segment, approximately 0.5 miles east of the Wamsutter/Crooks Gap Road, facing east.



d) Entering main Permit Area, facing south-southeast.

